U.S. NUCLEAR REGULATORY COMMISSION

REGION III

Reports No. 50-266/83-05(DRMS); 50-301/83-05(DRMS)

Docket Nos. 50-266; 50-301 Licenses No. DPR-24; DPR-27 Safeguards Group: IV

Licensee: Wisconsin Electric Power Company

231 W. Michigan Milwaukee, WI 53201

Facility Name: Point Beach Nuclear Plant, Units 1 and 2

Inspection At: Point Beach Site, Two Rivers, WI

Inspection Conducted: February 7-11, 1983

Date of Last Physical Security Inspection: August 9-13, 1982

Type of Inspection: Unannounced Physical Protection

Inspectors:

estur. E.C.

G. L. Pirtle

Physical Protection Specialist

G. M. Christoffer

Physical Protection Specialist

Approved By:

J. R. Creed, Chief

Safeguards Section

Inspection Summary:

Inspection on February 7-11, 1983 (Reports No. 50-266/83-05(DRMS);

50-301/83-05(DRMS))

Areas Inspected: Included Security Plan and Implementing Procedures; Security Organization - Reponse; Security Program Audit; Records and Reports; Testing and Maintenance; Locks, Keys, and Combinations; Physical Barriers - Protected and Vital Areas; Security System Power Supply; Lighting; Assessment Aids; Access Control - Personnel, Packages, and Vehicles; Detection Aids - Protected and Vital Areas; Safeguards Contingency Plan; Licensee's Actions on Previous Inspection Items; and Independent Inspection Effort. The inspection involved 83 inspector-hours by two NRC inspectors. The inspection began during the day shift; 22 of the 83 hours were accomplished during the off-shift periods.

SAFEGUARDS INFORMATION Upon Separation This Page is Decontrolled

8303170459 830314 PDR ADOCK 05000266 Q PDR Results: The licensee was found to be in compliance with NRC requirements within the areas examined during this inspection, except for the following items:

- 1. Access Control Personnel: Some required documentation was not available. (Paragraph 17)
- 2. Detection Aids Protected Area: The protected area intrusion alarm system did not detect all test penetrations conducted by the inspectors. (Paragraph 20)

An item of noncompliance from the previous inspection pertaining to failure to properly maintain an item of equipment within the Central Alarm Station was not closed. The licensee made various commitments pertaining to the closed circuit television system, maintenance requests, an audit item, documentation of certain actions, and posting of a security badge listing.

(DETAILS - UNCLASSIFIED SAFEGUARDS INFORMATION)

Enclosure Contains
SAFEGUARDS INFORMATION
Upon Separation This
Page is Decontrolled