Brunswick Nuclear Plant P.O. Box 10429 Southport, NC 28461-0429

MAY 26 1994

SERIAL: BSEP 94-0172

U. S. Nuclear Regulatory Commission ATTENTION: Document Control Desk Washington, DC 20555

BRUNSWICK STEAM LECTRIC PLANT, UNIT NOS. 1 AND 2 DOCKET NOS, 50-325 & 50-324/LICENSE NOS, DPR-71 & DPR-62 SUPPLEMENTAL RESPONSE TO NRC BULLETIN 90-01, SUPPLEMENT 1 REQUESTED ACTION 1.f

Gentlemen:

On March 8, 1993 (Serial: NLS-93-067), Carolina Power & Light Company (CP&L) submitted a response to NRC Bulletin 90-01, Supplement 1 "Loss of Fill-Oil in Transmitters Manufactured by Rosemount" for the Brunswick Nuclear Plant (BNP). In our response to requested Action 1.f, CP&L stated "Rosemount transmitters at BSEP which normally operate at pressures less than 500 psi will be excluded from the enhanced surveillance program."

As discussed with your staff on March 23, 1994, CP&L believes the response to Bulletin 90-01 adequately addressed the concerns identified, since loss of fill oil problems with Rosemount transmitters with an operating pressure up to 500 psi have not been experienced at BNP. CP&L also provided training to BNP instrumentation and control (i&C) maintenance technicians to ensure they are capable of recognizing and appropriately addressing sluggish transmitter responses. In addition, CP&L is including symptoms of oil loss associated with Rosemount transmitters during continuing training to I&C maintenance technicians.

If you have any further questions, please contact Mr. R. P. Lopriore Manager-Regulatory Affairs at (910) 457-2212.

Very truly yours,

J. Cowan, Director-Site Operations

Brunswick Nuclear Plant

4. 206

JCP/jcp (BNP94172.FIN) Enclosure

Mr. S. D. Ebneter, Regional Administrator, Region II

Mr. P. D. Milano, NRR Senior Project Manager - Brunswick Units 1 and 2

Mr. R. L. Prevatte, Brunswick NRC Senior Resident Inspector

9406010253 940 PDR ADDCK 05000324

Enclosure List of Regulatory Commitments

The following table identifies those actions committed to by Carolina Power & Light Company in this document. Any other actions discussed in the submittal represent intended or planned actions by Carolina Power & Light Company. They are described to the NRC for the NRC's information and are not regulatory commitments. Please notify the Manager-Regulatory Affairs at the Brunswick Nuclear Plant of any questions regarding this document or any associated regulatory commitments.

	Commitment	Committed date or outage
1.	CP&L is including symptoms of oil loss associated with Rosemount transmitters during continuing training to I&C maintenance technicians.	Not Specified