

Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION
P.O. BOX 128
SAN CLEMENTE, CALIFORNIA 92672

H. B. RAY
STATION MANAGER

February 23, 1983

RECEIVED
1983 MAR -7 PM 1:57
REGION V
SCE
TELEPHONE
(714) 492-7700

U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region V
1450 Maria Lane, Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. R. H. Engelken, Regional Administrator

Dear Sir:

Subject: Docket No. 50-361
30-Day Report
Licensee Event Report No. 83-017
San Onofre Nuclear Generating Station, Unit 2

Pursuant to Section 6.9.1.13.b of Appendix A Technical Specifications to Facility Operating License NPF-10 for San Onofre, Unit 2, this submittal provides the required 30-day written report and a copy of the Licensee Event Report (LER) form for an occurrence involving Limiting Condition for Operation 3.3.3.1 associated with the containment high range radiation monitor. Enclosed LER 83-017 addresses this event, including corrective actions and measures to prevent recurrence.

If there are any questions regarding this event, please so advise.

Sincerely,

HB Ray / RHC/ML

Enclosure: LER 83-017

cc: A.E. Chaffee (USNRC Resident Inspector, San Onofre, Units 2 and 3)
R.J. Pate (USNRC Resident Inspector, San Onofre, Units 2 and 3)

U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement

U.S. Nuclear Regulatory Commission
Office of Management Information and Program Control

Institute of Nuclear Power Operations (INPO)

8303180265 830223
PDR ADOCK 05000361
S PDR

IE-22
83-98