

PUBLIC SERVICE INDIANA

S. W. Shields Senior Vice President -Nuclear Division

.

September 10, 1982 S82-20 SVP-0021-82

Mr. James G. Keppler, Regional Administrator U. S. Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, Illinois 60137 Docket Nos.: STN 50-546 STN 50-547 Construction Permit Nos.: CPPR - 170 CPPR - 171

Marble Hill Nuclear Generating Station - Units 1 and 2

Dear Mr. Keppler:


On August 11, 1982, Mr. T. D. Geib of Public Service Company of Indiana, Inc. (PSI) notified your office of a potentially reportable item as required by 10 CFR 50.55(e). Contrary to procedure, the disposition of a contractor nonconformance report (NCR) was approved without design subcontractor review of the affected equipment. The subject NCR had been written to document removal of seismic uplift restraints from the containment polar crane due to an installation interference. Furthermore, the disposition of this NCR did not prescribe corrective action to reattach the restraints after installation was complete.

PSI Quality Assurance personnel have documented this item on a corrective action request and have initiated action to reopen and redisposition the contractor NCR. A review of similar NCR's which may have been dispositioned without appropriate design subcontractor review will also be initiated.

This letter is intended to fulfill the requirements of an interim report as required by 10 CFR 50.55(e). A further report will be filed on or before December 20, 1982. If you have any questions, please feel free to contact me.

Sincerely, S. W. Shields

SWS/TDG/bak



P. O. Box 190, New Washington, Indiana 47162

1E19

DMB



10

SERVICE INDIANA Letter: J. G. Keppler

-2-

September 10, 1982 S82-20 SVP-0021-82

cc: Director of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

J. E. Konklin J. J. Harrison