

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 N J S G S 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 _____ 5
 7 8 9 14 15 25 26 30 57 CAT 58

CON'T
 01 REPORT SOURCE L 6 0 5 0 0 0 2 7 2 7 0 2 2 2 8 3 8 0 3 1 0 8 3 9
 7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 On February 22, 1983, during a routine startup of Salem Unit 1, the reactor was
 03 manually tripped due to rapidly decreasing steam generator levels. Approximately 3
 04 seconds before the manual trip, both reactor trip breakers failed to open automatically
 05 on receipt of a valid Low-Low Steam Generator Level reactor trip signal. The fact that
 06 both breakers had failed was obscured by the manual trip, and the ensuing investi-
 07 gation therefore focused on the reasons for the manual trip and the related events.

08 _____

09 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
 I A 11 Z 12 C K T B R K 14 A 15 Z 16
 7 8 9 10 11 12 13 14 15 16 17 18 19 20

17 LER NO. REPORT NUMBER 8 3 21 22
 EVENT YEAR 8 3 21 22
 SEQUENTIAL REPORT NO. 0 1 2 24 26
 OCCURRENCE CODE 0 1 28 29
 REPORT TYPE 2 30 31
 REVISION NO. 0 32

ACTION TAKEN Z 18 X 19 EFFECT ON PLANT C 20 SHUTDOWN METHOD B 21 HOURS X X X X 22 ATTACHMENT SUBMITTED Y 23 NPRD-4 FORM SUB. Y 24 PRIME COMP. SUPPLIER A 25 COMPONENT MANUFACTURER W 1 2 0 26
 33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Following a similar occurrence on February 25, 1983, the plant was placed in a safe
 11 shutdown condition. Letters to the NRC dated March 1, and 8, 1983, provide docu-
 12 mentation of the investigation of the incident and proposed corrective action. A
 13 Supplemental Report will be submitted documenting the occurrence in detail.

14 _____

15 FACILITY STATUS C 28 % POWER 0 2 0 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operational Event 32
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

16 ACTIVITY CONTENT Z 33 Z 34 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

17 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION N/A 39
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

18 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION N/A 41
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

20 PUBLICITY ISSUED N 44 DESCRIPTION N/A 45
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

8303180425 830311
 PDR ADOCK 05000272
 S PDR

NRC USE ONLY

NAME OF PREPARER R. Frahm

PHONE: 609/935-6000 Ext. 3078