

*Southern California Edison Company*



SAN ONOFRE NUCLEAR GENERATING STATION

P.O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

March 7, 1983

TELEPHONE  
(714) 492-7700

H. B. RAY  
STATION MANAGER

U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region V  
1450 Maria Lane, Suite 210  
Walnut Creek, California 94596-5368

Attention: Mr. R. H. Engelken, Regional Administrator

Dear Sir:

Subject: Docket No. 50-362  
30-Day Report  
Licensee Event Report No. 83-017  
San Onofre Nuclear Generating Station, Unit 3

Reference: Letter, H.B. Ray (SCE) to R.H. Engelken (NRC),  
dated February 24, 1983

Pursuant to Section 6.9.1.13.b of Appendix A, Technical Specifications to Facility Operating License NPF-15 for San Onofre Unit 3, this submittal provides the required 30-day written report and a copy of Licensee Event Report (LER) for an occurrence involving Limiting Condition of Operation (LCO) 3.5.1 associated with Safety Injection Tanks. Enclosed LER 83-017 addresses this event, including corrective actions and measures to prevent recurrence.

If there are any questions regarding the above, please contact me.

Sincerely,

8303180486 830307  
PDR ADOCK 05000362  
S PDR

Attachments

cc: A. E. Chaffee (USNRC Resident Inspector, San Onofre Units 2 & 3)  
R. J. Pate (USNRC Resident Inspector, San Onofre Units 2 & 3)

U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement

U. S. Nuclear Regulatory Commission  
Office of Management Information and Program Control

Institute of Nuclear Power Operations

RECEIVED  
MAR 10 AM 11:07  
1983

IE-22  
83-105