



ATLAS CORPORATION | 

Republic Plaza, 370 Seventeenth Street, Suite 3150
Denver, CO 80202
Telephone: (303) 825-1200 Fax: (303) 892-8808

May 31, 1994

DELIVERED BY FEDERAL EXPRESS

Mr. Joseph J. Holonich
Uranium Recovery Branch
U. S. Nuclear Regulatory Commission
Division of Low-Level Waste Management
and Decommissioning
NMSS (5 E2)
11555 Rockville Pike
Rockville, MD 20850

Re: License SUA-917
Docket No. 40-3453
November 29, 1993 and
January 3, 1994 Requests
for Information

Dear Mr. Holonich:

Transmitted herewith is Atlas Corporation's (Atlas') response to the Nuclear Regulatory Commission's (NRC's) requests for information dated November 29, 1993, and January 3, 1994. This submittal addresses faulting, seismic, geomorphic, erosion control and radon attenuation issues and completes our responses to the comments provided in these information requests. A previous response to the November 29, 1993, request for information was submitted to NRC on January 28, 1994.

This response includes documents prepared by Woodward-Clyde Federal Services Corp. (faulting issues) and Mussetter Engineering, Inc. (geomorphic issues). The Woodward-Clyde document was submitted to the Utah Geological Survey and they were in general agreement with the response.

NLOS
11/1


Mr. Joseph J. Holonich

2

May 27, 1994

We trust that the responses to the comments adequately address the issues of concern. If you have any questions concerning this submittal, please call me at (303) 825-1200.

Sincerely,


for Richard E. Blubaugh

Richard E. Blubaugh
Vice President, Environmental
and Governmental Affairs

REB/ajw

Enclosures