

50.55(e) Report RECEIVED NRC

Arizona Public Service Company

P.O. BOX 21666 • PHOENIX, ARIZONA 85036

MAR 14 AM 11:22

March 10, 1983
ANPP-23222-GHD/BSK

U. S. Nuclear Regulatory Commission
Region V
Creekside Oaks Office Park
1450 Maria Lane - Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. D. M. Sternberg, Chief
Reactor Projects Branch 1

Subject: Time Extension For Report - DER 82-73
A 50.55(e) Potentially Reportable Deficiency Relating to
ITT Grinnell Pipe Support Clamps In Unit 2 MSSS Have Excess
Gap, May Not Properly Secure Pipe
File: 83-019-026
D.4.33.2

Reference: (A) Telephone Conversation between P. Narbut and
G. Duckworth on November 24, 1982
(B) ANPP-22589, dated December 23, 1982 (Interim Report)


Dear Sir:

The NRC was notified of a potentially reportable deficiency in
Reference (A), an Interim Report was transmitted by Reference (B). At
that time, it was estimated that a Final Report would be available by
March 9, 1983.

Due to the extensive evaluation required, it is now expected that this
information will be finalized by April 21, 1983, when a complete report
will be submitted.

There is no change to the Interim Report at this time.

Very truly yours,



E. E. Van Brunt, Jr.
APS Vice President
Nuclear Projects Management
ANPP Project Director

EEVBJr/GHD:db

cc: See Attached Page 2

1E27

U. S. Nuclear Regulatory Commission.
Attention: Mr. D. M. Sternberg, Chief
Page 2

March 10, 1983
ANPP-23222-GHD/BSK

cc: Richard DeYoung, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

T. G. Woods, Jr.
J. A. Roedel
D. B. Fasnacht
G. C. Andognini
J. R. Bynum
A. C. Rogers
B. S. Kaplan
W. E. Ide
J. Vorees
P. P. Klute/D. D. Green
A. C. Gehr
W. J. Stubblefield
W. G. Bingham
R. L. Patterson
R. W. Welcher
R. M. Grant
D. R. Hawkinson
L. E. Vorderbrueggen
G. A. Fiorelli