Huron Road Hospital ATTN: Mr. E. Notebaert Chief Executive Officer 13951 Terrace Road East Cleveland, OH 44112

License No. 34-01505-01

30-2680

Gentlemen:

This refers to the routine safety inspection conducted by Ms. T. L. Simmons of this office on March 2, 1983, of activities authorized by NRC Byproduct Material License No. 34-01505-01 and to the discussion of our findings with Ms. J. Hausrath and Mr. G. Moebius at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

In addition to the above areas, the inspector examined actions described in your letter dated May 7, 1980, regarding apparent items of noncompliance found during our March 21, 1980 inspection. We have no further questions regarding these matters.

During this inspection, certain of your activities appeared to be in noncompliance with NRC requirements, as specified in the enclosed Appendix. A written response is required.

The responses directed by this letter (and the accompanying Notice) are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

R. Miller, Chief Materials and Safeguards Branch

Enclosure: Appendix, Notice of Violation

cc w/encl: Mr. G. Moebius

DMB/Document Control Desk (RIDS)

RIII

Simmons/jp Sreniawski 3/17/83 3/17/83

DMB. 1E 07 Capy

8303220194 830318 NMS LIC30 PDR 34-01505-01