In Reply Refer To: Docket: 50-267

MAR 1 4 1983

Mr. O. R. Lee, Vice President Electric Production Public Service Company of Colorado P.O. Box 840 Denver, Colorado 80201

Dear Mr. Lee:

We are continuing our review of the Fort St. Vrain compliance with the NRC positions presented in NUREG-0737, Item III.D.3.4., "Control Room Habitability." As a result of our review of the information that you have provided, including your November 18, 1982, letter (P-82526) in response to inquiries by P. Wagner, we have determined that the Fort St. Vrain system does not appear to meet the single-failure criteria, in that the failure of a single fan or damper could disable the system and prevent it from performing its safety function.

As indicated in Figure 1 of Attachment 4 to your December 20, 1080, response (P-80438) the failure of dampers V75432, V75449, or V75407 could prevent control room isolation. Also, the failure of the supply fan C7504 or the return fan C7505 to operate, or the failure of either dampers V75405 or V75406 could disable the system.

Therefore, we request that you submit, within 45 days of your receipt of this letter, either an analysis or proposed modifications which demonstrate a control room habitability system capable of functioning with a single failure an active component.

Since this request affects fewer than ten respondents, OMB clearance is not required under P.L. 96-511.

RPB1 (w) PWagner/dsm 3/9/83 RPB1 GMadsen 3/4/83

DRRP&EP/RIV JGagliardo 3/ /83

4005

B303250135 830314 PDR ADOCK 05000267 PDR ADOCK 05000267 Mr. O. R. Lee

2

If you have any questions on this matter, please contact your project manager.

Sincerely,

"Original Signed by: T. F. WESTERMAN"

G. L. Madsen, Chief Reactor Project Branch 1

cc: See Attached List

Fort St. Vrain

C. K. Millen
Senior Vice President
Put C Service Company
of Colorado
P. O. Box 840
Denver, Colorado 30201

James B. Graham, Manager Licensing and Regulation East Coast Office General Atomic Company 2021 K Street, NW, Suite 709 Washington, DC 20006

J. K. Fuller, Vice President
Public Service Company
of Colorado
P. O. Box 840
Denver, Colorado 80201

M. W. Dickerson NRC Senior Resident Inspector P. O. Box 640 Platteville, Colorado 80651

Director, Division of Planning Department of Local Affairs 615 Columbine Building 1845 Sherman Street Denver, Colorado 80203 Chairman, Board of County Commissioners of Weld County, Colorado Greeley, Colorado 80631

Regional Representative Radiation Programs Ervironmental Protection Agency 1860 Lincoln Street Denver, Colorado 80203

Don Warembourg Nuclear Production Manager Public Service Company of Colorado P. O. Box 368 Platteville, Colorado 80651

Darrell G. Eisenhut, Director Division of Licensing Office of Nuclear Reactor Regulation U.S. Nuclear Regulatory Commission Washington, D.C. 20555