



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011-8064

MIN - 3 1994

Docket: 50-382
License: NPF-38

Entergy Operations, Inc.
ATTN: Ross P. Barkhurst, Vice President
Operations, Waterford
P.O. Box B
Killona, Louisiana 70066

SUBJECT: NRC INSPECTION REPORT 50-382/94-08 (NOTICE OF VIOLATION)

This refers to the inspection conducted by E. J. Ford and others of this office on March 6 through April 16, 1994. The inspection included a review of activities authorized for your Waterford Steam Electric Station, Unit 3, facility. At the conclusion of the inspection, the findings were discussed with you and those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress. The purpose of the inspection was to determine whether activities authorized by the license were conducted safely and in accordance with NRC requirements.

Based on the results of this inspection, certain licensed activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice of Violation (Notice). This violation is of concern for two reasons: (1) the lack of attention to detail by your staff regarding adherence to radiation protection requirements for a contaminated area; and (2) the lack of a questioning attitude by your health physics staff. These resulted in missed opportunities to review radiation work permit (RWP) requirements and to remove an individual from the contaminated area, when the infraction was initially brought to your staff's attention.

One unresolved item was identified concerning the absence of an engineering evaluation for impact on plant operability, when unsecured lifting slings were discovered on top of the pressurizer cubicle during plant heatup. This matter is discussed in Section 3.1.4 of the enclosed inspection report.

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. In your response, you should document the specific actions taken and any additional actions you plan to prevent recurrence. After reviewing your response to this Notice, including your proposed corrective actions and the results of future inspections, the NRC will determine whether further NRC enforcement action is necessary to ensure compliance with NRC regulatory requirements.

9406100057 940603
PDR ADOCK 05000382
G PDR


TEO
11

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosures will be placed in the NRC Public Document Room.

The responses directed by this letter and the enclosed Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, Pub. L. No. 96.511.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,



A. Bill Beach, Director
Division of Reactor Projects

Enclosures:

1. Appendix A - Notice of Violation
2. Appendix B - NRC Inspection Report
50-382/94-08

cc w/enclosures:

Entergy Operations, Inc.
ATTN: Harry W. Keiser, Executive Vice
President and Chief Operating Officer
P.O. Box 31995
Jackson, Mississippi 39286-1995

Entergy Operations, Inc.
ATTN: Jerrold G. Dewease, Vice President
Operations Support
P.O. Box 31995
Jackson, Mississippi 39286-1995

Wise, Carter, Child & Caraway
ATTN: Robert B. McGehee, Esq.
P.O. Box 651
Jackson, Mississippi 39205

Entergy Operations, Inc.
ATTN: D. F. Packer, General
Manager Plant Operations
P.O. Box B
Killona, Louisiana 70066

Entergy Operations, Inc.

-3-

Entergy Operations, Inc.
ATTN: L. W. Laughlin
Licensing Manager
P.O. Box B
Killona, Louisiana 70066

Chairman
Louisiana Public Service Commission
One American Place, Suite 1630
Baton Rouge, Louisiana 70825-1697

Entergy Operations, Inc.
ATTN: R. F. Burski, Director
Nuclear Safety
P.O. Box B
Killona, Louisiana 70066

William H. Spell, Administrator
Radiation Protection Division
P.O. Box 82135
Baton Rouge, Louisiana 70884-2135

Parish President
St. Charles Parish
P.O. Box 302
Hahnville, Louisiana 70057

Mr. William A. Cross
Bethesda Licensing Office
3 Metro Center
Suite 610
Bethesda, Maryland 20814

Winston & Strawn
ATTN: Nicholas S. Reynolds, Esq.
1400 L Street, N.W.
Washington, D.C. 20005-3502

E-Mail report to D. Sullivan (DJS)

bcc to DMB (IE01)

bcc distrib. by RIV:

L. J. Callan

Branch Chief (DRP/J)

MIS System

RIV File

Project Engineer (DKP/D)

Resident Inspector

Lisa Shea, RM/ALF, MS: MNBB 4503

DRSS-FIPB

Branch Chief (DRP/TSS)

A. B. Beach, D:DRP

RIV:RI <i>for</i>	SRI <i>for</i>	C:DRP/D <i>for</i>	D:DRP <i>for</i>	
JDixon-Herrity	EJFord	TFStetka	ABBeach	
6/1/94	6/1/94	6/1/94	6/3/94	

E-Mail report to D. Sullivan (DJS)

bcc to DMB (IE01)

bcc distrib. by RIV:
L. J. Callan
Branch Chief (DRP/D)
MIS System
RIV File
Project Engineer (DRP/D)

Resident Inspector
Lisa Shea, RM/ALF, MS: MNBB 4503
DRSS-FIPB
Branch Chief (DRP/TSS)
A. B. Beach, D:DRP

RIV:RI <i>for</i>	SRI <i>for</i>	C:DRP/D <i>for</i>	D:DRP <i>for</i>	
JDixon-Herrity	EJFord	TFStetka	ABBeath	
6/1/94	6/1/94	6/1/94	6/3/94	

090041