UNITED STATES OF AMERICA NUCLEAR REGULATORY COMMISSION

In the Matter of

Docket No. 50-293

BOSTON EDISON COMPANY

(Pilgrim Nuclear Power Station)

ORDER CONFIRMING LICENSEE COMMITMENTS ON POST-TMI RELATED ISSUES

Ι.

The Boston Edison Company (the licensee) is the holder of Facility Operating License No. DPR-35 which authorizes the operation of the Pilgrim Nuclear Power Station (the facility) at steady-state power levels not in excess of 1998 megawatts thermal. The facility is a boiling water reactor (BWR) located at the licensee's site in Plymouth County, Massachusetts.

II.

Following the accident at Three Mile Island Unit No. 2 (TMI-2) on March 28, 1979, the Nuclear Regulatory Commission (NRC) staff developed a number of proposed requirements to be implemented on operating reactors and on plants under construction. These requirements include Operational Safety, Siting and Design, and Emergency Preparedness and are intended to provide substantial

additional protection in the operation of nuclear facilities based on the experience from the accident at TMI-2 and the official studies and investigations of the accident. The staff's proposed requirements and schedule for implementation are set forth in NUREG-0737, "Clarification of TMI Action Plan Requirements." Among these requirements are a number of items, consisting of hardware modifications, administrative procedure implementation and specific information to be submitted by the licensee, scheduled to be completed on or after July 1, 1981. On March 17, 1982, a letter (Generic Letter 82-05) was sent to all licensees of operating power reactors for those items that were scheduled to be implemented from July 1, 1981 through March 1, 1982. Subsequently, on May 5, 1982, a letter (Generic Letter 82-10) was also sent to all licensees of operating power reactors for those items that were scheduled for implementation after March 1, 1982. These letters are hereby incorporated by reference. In these letters each licensee was requested to furnish within 30 days pursuant to 10 CFR 50.54(f) the following information for items which the staff had proposed for completion on or after July 1, 1981:

(1) For applicable items that have been completed, confirmation of completion and the date of completion, (2) For items that have not been completed, a specific schedule for implementation, which the licensee committed to meet, and (3) Justification for delay, demonstration of need for the proposed schedule, and a description of the interim compensatory measures being taken.

III.

The licensee responded to Generic Letter 82-05 by letters dated April 16, and June 9, 1982; the licensee responded to Generic Letter 82-10 by letters dated June 8 and 9, 1982 and January 28, 1983. In these submittals, the licensee confirmed that some of the items identified in the Generic Letters had been completed, took technical exception to two items, and made firm commitments to complete the remainder. The attached Tables summarizing the licensee's schedular commitments or status were developed by the staff from the Generic Letters and the licensee-provided information.

Generic Letters 82-05 and 82-10 applied to 16 and 10 items, respectively, for BWRs with jet-pumps. Of the ten items listed in Generic Letter 82-10, six items are not included in this Order. Item I.A.1.3.2 is part of a separate rulemaking; Items I.C.1, III.A.1.2 (2 items), and III.A.2.2 will be handled separately following Commission actions that would proceed as a result of its consideration of SECY 82-111, as amended; and Item II.K.3.30 and II.K.3.31 (one item) is not required until one year after staff approval of the generic model and staff review of these models has not been completed.

Eighteen of the 20 items addressed in this Order are considered by the licensee to be completed or to require no modifications. The licensee is taking technical exception to two items (II.E.4.2.7 and II.K.3.22); these items will be addressed in a separate action and are therefore not included in this Order. The staff's evaluation of the licensee's delays for the remaining two items is provided herein:

II.B.3 Post-Accident Sampling and

II.F.1(6) Post-Accident Monitoring System

In order to re-plan and integrate all construction activities in an effort to control the overall magnitude of these activities and provide adequate assurance for reducing potential safety hazards, modification work on these two items was stopped in March 1982. In view of the intense construction activity associated with ongoing modification work at the time, this suspension of activity was necessary to enable effective management and control of available resources and to assure improved control of these and other necessary safety-related modifications.

The licensee will use existing systems and interim procedures for events which might reasonably be expected to occur during the period until these systems are installed and operational. Interim procedures for obtaining primary containment gas samples and reactor water samples have been implemented at Pilgrim. In addition, two redundant hydrogen analyzers and one oxygen analyzer are presently installed at Pilgrim to measure containment atmosphere hydrogen and oxygen content.

We find, based on the above evaluation, that: 1) the licensee has taken corrective actions regarding the delays and has made a responsible effort to implement the NUREG-0737 requirements noted; 2) there is good cause for the several delays; and 3) as noted above, interim compensatory measures have been provided.

In view of the foregoing, I have determined that these modifications and actions are required in the interest of public health and safety and, therefore, the licensee's commitment should be confirmed by Order.

Accordingly, pursuant to Sections 103, 161i, and 161o of the Atomic Energy Act of 1954, as amended, and the Commission's regulations in 10 CFR Parts 2 and 50, IT IS HEREBY ORDERED EFFECTIVE IMMEDIATELY THAT THE LICENSEE SHALL:

> Implement and maintain the specific items described in the Attachments to this Order in the manner described in the licensee's submittals noted in Section III herein no later than the dates in the Attachments.

> > ٧.

The licensee may request a hearing on this Order within 20 days of the date of publication of this Order in the <u>Federal Register</u>. A request for a hearing shall be addressed to the Director, Office of Nuclear Reactor Regulation, U.S. Nuclear Regulatory Commission, Washington, D.C. 20555. A copy shall also be sent to the Executive Legal Director at the same address. A REQUEST FOR HEARING SHALL NOT STAY THE IMMEDIATE EFFECTIVENESS OF THIS ORDER.

If a hearing is requested by the licensee, the Commission will issue an Order designating the time and place of any such hearing.

If a hearing is held concerning this Order, the issue to be considered at the hearing shall be whether the licensee should comply with the requirements set forth in Section IV of this Order. This Order is effective upon issuance.

FOR THE NUCLEAR REGULATORY COMMISSION

Tolen Sidenple

Robert A. Purple, Deputy Director Division of Licensing Office of Nuclear Reactor Regulation

Dated at Bethesda, Maryland, this 14th day of March 1983.

Attachments:

- Licensee's Commitments on Applicable NUREG-0737 Requirements from Generic Letter 82-05
- Licensee's Commitments on Applicable NUREG-0737 Requirements from Generic Letter 82-10

Attachment 1

LICENSEE'S COMMITMENTS ON APPLICABLE NUREG-0737 ITEMS FROM GENERIC LETTER 82-05

Item	Title	NUREG-0737 Schedule	Requirement	Licensee's Completion Schedule (or status)
I.A.3.1	Simulator Exams	10/1/81	Include simulator exams in licensing examinations	Complete
II.B.2	Plant Shielding	1/1/82	Modify facility to provide access to vital areas under accident conditions	Complete
II.B.3	Post-Accident Sampling	1/1/82	Install upgraded post-accident sampling capability	6/1/84
11.8.4	Training for Mitigating Core Damage	10/1/81	Complete training program	Complete
II.E.4.2	Containment Isolation Dependability	7/1/81	Part 5-lower con- tainment pressure setpoint to level compatible w/normal operation	Complete
		7/1/81	Part 7-isolate purge* & vent valves on radiation signal	Technical Exception
II.F.1	Accident Monitoring	1/1/82	<pre>(1) Install noble gas effluent monitors</pre>	Complete
		1/1/82	(2) Provide capa- bility for effluent monitoring of iodine	Complete
		1/1/82	<pre>(3) Install incon- tainment radiation- level monitors</pre>	Complete

Page 2

Attachment 1

LICENSEE'S COMMITMENTS ON APPLICABLE NUREG-0737 ITEMS FROM GENERIC LETTER 82-05

Item	Title	NUREG-0737	Requirement	Licensee's Completion Schedule
II.F.1		1/1/82	<pre>(4) Provide con- tinuous indication of containment</pre>	Complete
		1/1/82	pressure (5) Provide con- tinuous indication of containment	Complete
		1/1/82	water level (6) Provide con- tinuous indication of hydrogen con- centration in containment	6/1/84
II.K.3.15	Isolation of HPCI & RCIC Modification	7/1/81	Modify pipe break detection logic to prevent inadvertent isolation	Complete
II.K.3.22	RCIC Suction*	1/1/82	Modify design of RCIC suction to provide automatic transfer to torus	Technical Exception
II.K.3.24	Space Cooling for HPCI/RCIC	1/1/82	Confirm the adequacy of space cooling for HPCI/RCIC	Complete
II.K.3.27	Common reference level	7/1/81	Provide common reference level for vessel level instru- mentation	Complete

Attachment 2

LICENSEE'S COMMITMENTS ON APPLICABLE NUREG-0737 ITEMS FROM GENERIC LETTER 82-10

Item	Title	NUREG-0737	Requirement	Licensee's Completion Schedule
1.A.1.3.1	Limit Overtime	10/1/82 per Gen. Ltr. 82-12 dtd 6/15/82	Revise administra- tive procedures to limit overtime in accordance w/NRC Policy Statement issued by Generic Ltr. No. 82-12, dtd 6/15/82	Complete
1.A.1.3.2	Minimum Shift* Crew	To be super- seded by Proposed Rule	To be addressed in the Final Rule on Licensed Operator Staffing at Nuclear Power Units	To be addressed when Final Rule is issued
1.C.1	Revise Emergency* Procedures	Superseded by SECY 82-111	Reference SECY 82-111, Requirements for Emergency Re- sponse Capability	To be determined
II.D.1.2	RV and SV Test Programs	1/1/82	Submit plant speci- fic reports on relief and safety valve program	Complete
II.K.3.18	ADS Actuation	9/30/82	Submit revised position on need for modifications	Complete
II.K.3.30 & 31	SBLOCA Analysis*	l yr. after staff approval of model	Submit plant speci- fic analyses	To be determined following staff approval of model
III.A.1.2	Staffing Levels* for Emergency Situations	Superseded by SECY 82-111	Reference SECY 82- 111, Requirements for Emergency Response Capability	To be determined

Page 2

Attachment 2

LICENSEE'S COMMITMENTS ON APPLICABLE NUREG-0737 ITEMS FROM GENERIC LETTER 82-10

Item	Title	NUREG-0737	Requirement	Licensee's Completion Schedule (or status)
111.A.1.2	Upgrade Emer* gency Support Facilities	Superseded by SECY 82-111	Reference SECY 82- 111, Requirements for Emergency Response Capability	To be determined
111.4.2.2	Meteorological* Data	Superseded by SECY 82-111	Reference SECY 82- 111, Requirements for Emergency Response Capability	To be determined
III.D.3.4	Control Room Habitability	To be Determined by licensee	Modify facility as identified by licensee study	Complete