

UPDATE LICENSEE EVENT REPORT PREVIOUS REPORT DATE 9/24/82

CONTROL BLOCK: [] [] [] [] [] [] [] [] [] [] [] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[0][1] [M][A][P][P][S][1] [2] [0][0]-[0][0][0][0][0][0]-[0][0] [3] [4][1][1][1][1] [4] [5]
7 8 9 14 15 25 26 30 57 58
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T [0][1] REPORT SOURCE [L] [6] [0][5][0]-[0][2][9][3] [7] [0][8][2][6][8][2] [8] [1][0][0][1][8][2] [9]
7 8 60 61 68 69 74 75 80
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

[0][2] On 8/26/82, both HPCI area smoke detector systems were made inoperable to perform
[0][3] corrective maintenance. T.S. requires one system in the HPCI areas to be operable.
[0][4] A fire patrol was established prior to inoperability. This event caused no
[0][5] threat to the public health and safety.
[0][6]
[0][7]
[0][8]

[0][9] [A][B] [11] [E] [12] [G] [13] [I][N][S][T][R][U] [14] [E] [15] [Z] [16]
7 8 9 10 11 12 13 18 19 20
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
[17] [8][2] [] [0][3][4] [] [0][3] [X] [] [1]
21 22 23 24 26 27 28 29 30 31 32
LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
ACTION TAKEN [B] [18] [F] [19] EFFECT ON PLANT [Z] [20] SHUTDOWN METHOD [Z] [21] HOURS [0][0][0][0] ATTACHMENT SUBMITTED [N] [23] NPRD-4 FORM SUB. [N] [24] PRIME COMP. SUPPLIER [L] [25] COMPONENT MANUFACTURER [X][9][9][9] [26]
33 34 35 36 37 40 41 42 43 44 47
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

[1][0] Moisture from a steam leak condensed inside the detectors causing them to give
[1][1] a false smoke indication. The detectors were removed, replaced and functionally
[1][2] tested per procedure. An engineering support request has been issued to provide
[1][3] a long-term fix. The detectors are Simplex Time Recorder Co. Model #4259-35.
[1][4]

[1][5] [E] [28] [1][0][0] [29] NA [A] [31] Operational Event
7 8 9 10 12 13 44 45 46 80
FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)
[1][6] [Z] [33] [Z] [34] NA [] NA
7 8 9 10 11 44 45 80
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)
[1][7] [0][0][0] [37] [Z] [38] NA
7 8 9 11 12 13 80
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
[1][8] [0][0][0] [40] NA
7 8 9 11 12 80
PERSONNEL INJURIES NUMBER DESCRIPTION (41)
[1][9] [Z] [42] NA
7 8 9 10 80
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)

[2][0] [N] [44]
7 8 9 10 80
ISSUED DESCRIPTION (45) PUBLICITY

8210190237 821001
PDR ADDOCK 05000293
S PDR

NRC USE ONLY