

Automatic Switch Co.


Manufacturers of
DEPENDABLE CONTROL
Since 1888

ASCO®

FLORHAM PARK NEW JERSEY 07932 N.J.-(201) 966-2000 N.Y.-(212) 344-3765

March 10, 1983

U.S. Nuclear Regulatory Commission
Administrator Region 4
611 Ryan Plaza Drive
Suite 1000
Arlington, TX 76011



Subject: Possible recall per 10CFR21,
ASCO Catalog No. 386B180 Transfer Switches

Reference: Our letter dated January 13, 1983

Gentlemen:

As of 2/7/83, all five transfer switches located at Con Edison's Indian Point generating plant were inspected and adjusted where necessary. No further action is required on the five units.

We have incorporated into our Test and Adjustment procedure a requirement to review the sub-assembly for proper function to assure any further transfer switches manufactured will be properly adjusted. This test procedure number is FS-331-230.

No other units are installed in any other generating stations subject to 10CFR21.

Very truly yours,

AUTOMATIC SWITCH COMPANY

Hans R. Naumann
Vice President, Switch Dept.

HRN:mw

cc: L. Olsen, Manager, Q.C.
M. Balanson - Con Edison

8303280170 830310
PDR ADOCK 05000003
S PDR

TE:19
6137