

LICENSEE EVENT REPORT

CONTROL BLOCK: (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | C | A | S | O | S | 2 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5
7 8 9 14 15 25 26 30 57 CAT 58
LICENSEE CODE LICENSE NUMBER LICENSE TYPE

0 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 6 | 1 | 7 | 0 | 9 | 1 | 7 | 8 | 2 | 8 | 1 | 0 | 0 | 8 | 8 | 2 | 9
7 8 60 61 68 69 74 75 80
CON'T REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | While in Mode 2, the Condensate Storage Tank T-120 water level fell
0 3 | below the Technical Specification 3.7.1.3 limit. There was no consequence
0 4 | to public health and safety since there was no significant decay heat in
0 5 | the core.
0 6 |
0 7 |
0 8 |

0 9 | H | H | B | A | Z | Z | Z | Z | Z | Z | Z | Z | Z | Z | Z | Z | Z | L | 8 | 2 | 1 | 1 | 6 | 0 | 3 | L | 0 | X | F | Z | Z | 0 | 0 | 0 | 0 | N | N | Z | Z | 9 | 9 | 9 | 0
7 8 9 10 11 12 13 18 19 20 21 22 23 24 26 27 28 29 30 31 32
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
17 LER/RO REPORT NUMBER 21 EVENT YEAR 22 23 24 SEQUENTIAL REPORT NO. 26 27 OCCURRENCE CODE 28 29 REPORT TYPE 30 31 REVISION NO. 32
33 ACTION TAKEN 34 FUTURE ACTION 35 EFFECT ON PLANT 36 SHUT-DOWN METHOD 40 HOURS 41 ATTACHMENT SUBMITTED 42 NRPD-4 FORM SUB. 43 PRIME COMP. SUPPLIER 44 COMPONENT MANUFACTURER 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Inadequate makeup water control to Tank T-121 and a more restrictive than necessary
1 1 | Technical Specification limit were the cause. Corrective actions include a proposed
1 2 | Technical Specification change and a design change to install automatic level
1 3 | control systems (expected to be installed prior to 100% power operation).
1 4 |

1 5 | B | 0 | NA | A | Operator Observation
7 8 9 10 12 13 44 45 46
FACILITY STATUS 28 % POWER 29 OTHER STATUS 30 METHOD OF DISCOVERY 31 DISCOVERY DESCRIPTION 32

1 6 | Z | Z | NA | NA
7 8 9 10 11 44 45 46
ACTIVITY CONTENT 33 34 AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36

1 7 | 0 | 0 | 0 | Z | NA
7 8 9 10 11 12 13
PERSONNEL EXPOSURES 37 38 DESCRIPTION 39

1 8 | 0 | 0 | 0 | NA
7 8 9 10 11 12 13
PERSONNEL INJURIES 40 41 DESCRIPTION 41

1 9 | Z | NA
7 8 9 10 11 12
LOSS OF OR DAMAGE TO FACILITY TYPE 42 DESCRIPTION 43

2 0 | N |
7 8 9 10
PUBLICITY ISSUED DESCRIPTION 44 45

8210190317 821008
PDR ADOCK 05000361
S PDR

NAME OF PREPARER H. B. Ray

PHONE: 714/492-7700

NRC USE ONLY