

LICENSEE EVENT REPORT

CONTROL BLOCK: | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 C A S O S 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
CON'T
0 1 L 6 0 5 0 0 0 3 6 1 7 0 9 1 0 8 2 8 1 0 0 8 8 2 9
7 8 REPORT SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 While in Mode 2, the Condensate Storage Tank T-120 water level fell
0 3 below the Technical Specification 3.7.1.3 limit. There was no consequence
0 4 to public health and safety since there was no significant decay heat in
0 5 the core.
0 6
0 7
0 8

0 9 SYSTEM CODE: H H (11) CAUSE CODE: B (12) CAUSE SUBCODE: A (13) COMPONENT CODE: Z Z Z Z Z Z Z Z (14) COMP. SUBCODE: Z (15) VALVE SUBCODE: Z (16)
7 8 9 10 11 12 13 14 18 19 20

(17) LER/RO REPORT NUMBER: 8 2 (21) EVENT YEAR: 8 2 (22) SEQUENTIAL REPORT NO.: 1 1 2 (24) OCCURRENCE CODE: 0 3 (28) REPORT TYPE: L (30) REVISION NO.: 0 (32)
7 8 9 10 11 12 13 14 18 19 20 21 22 24 26 27 28 29 30 31 32

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Inadequate makeup water control to Tank T-121 and a more restrictive than necessary
1 1 Technical Specification limit were the cause. Corrective actions include a proposed
1 2 Technical Specification change and a design change to install automatic level
1 3 control systems (expected to be installed prior to 100% power operation).
1 4

1 5 FACILITY STATUS: B (28) % POWER: 0 (10) OTHER STATUS: NA (30) METHOD OF DISCOVERY: A (31) DISCOVERY DESCRIPTION: Operator Observation (32)
7 8 9 10 11 12 13 14 18 19 20 21 22 24 26 27 28 29 30 31 32
1 6 RELEASED OF RELEASE: Z (33) Z (34) AMOUNT OF ACTIVITY: NA (35) LOCATION OF RELEASE: NA (36)
7 8 9 10 11 12 13 14 18 19 20 21 22 24 26 27 28 29 30 31 32
1 7 PERSONNEL EXPOSURES: NUMBER: 0 0 0 (37) TYPE: Z (38) DESCRIPTION: NA (39)
7 8 9 10 11 12 13 14 18 19 20 21 22 24 26 27 28 29 30 31 32
1 8 PERSONNEL INJURIES: NUMBER: 0 0 0 (40) DESCRIPTION: NA (41)
7 8 9 10 11 12 13 14 18 19 20 21 22 24 26 27 28 29 30 31 32
1 9 LOSS OF OR DAMAGE TO FACILITY: TYPE: Z (42) DESCRIPTION: NA (43)
7 8 9 10 11 12 13 14 18 19 20 21 22 24 26 27 28 29 30 31 32

2 0 PUBLICITY ISSUED: N (44) DESCRIPTION: 8210190328 821008 PDR ADOCK 05000361 S PDR
7 8 9 10 11 12 13 14 18 19 20 21 22 24 26 27 28 29 30 31 32
NAME OF PREPARER: H. B. Ray
PHONE: 714/492-7700
P.O. 817-026