

APPENDIX A

Unibraze Corporation
Docket No. 99900793/83-01

NOTICE OF VIOLATION

As a result of the inspection conducted on January 10-14, 1983, and in accordance with Section 206 of the Energy Reorganization Act of 1974 and its implementing regulation 10 CFR Part 21, the following violation was identified and has been categorized in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C), 47 FR 9987 (March 9, 1982):

Section 21.6 of 10 CFR Part 21 dated September 1, 1982, states, in part:
"(a) Each . . . corporation . . . subject to the regulations in this part, shall post current copies of the following documents . . . (1) the regulations in this part"

Section 21.21 of 10 CFR Part 21 dated September 1, 1982, states, in part:
"(a) Each individual, corporation, partnership or other entity subject to the regulations in this part shall adopt appropriate procedures to: (1) provide for; (i) evaluating deviations; or (ii) informing the licensee or purchaser of the deviation in order that the licensee or purchaser may cause the deviation to be evaluated unless the deviation has been corrected"

Contrary to the above:

1. A current copy dated September 1, 1982, of 10 CFR Part 21 was not posted in the area where Section 206 was posted.
2. Appropriate procedures to evaluate deviations or inform the licensee or purchaser of the deviation did not exist.

This is a Severity Level V Violation (Supplement VII).