COVINGTON, OHIO

REPURT NO .:

99900793/83-01

INSPECTION DATE(S)

1/10-14/83

INSPECTION

ON-SITE HOURS: 31

CORRESPONDENCE ADDRESS:

Unibraze Corporation

ATTN: Mr. M. B. MacBryde

President

7502 W. State, Route 41 Covington, Ohio 45318

ORGANIZATIONAL CONTACT: Mr. C. R. Miller, QA Manager

TELEPHONE NUMBER:

(513) 473-2001

PRINCIPAL PRODUCT: Welding filler metals.

NUCLEAR INDUSTRY ACTIVITY: Approximately 1 percent of the CY 1982 sales.

ASSIGNED INSPECTOR:

Conway, Reactive and/Component Program

Section (R&CPS)

OTHER INSPECTOR(S):

APPROVED BY:

Barnes, Chief,

INSPECTION BASES AND SCOPE:

- A. BASES: 10 CFR Part 50, Appendix B and 10 CFR Part 21.
- B. SCOPE: This inspection was made as a result of the notification by the Tennessee Valley Authority of the furnishing of mixed diameter electrodes (1/8" and 5/32" in the same canister) to the Hartsville nuclear site. In addition, the following programmatic areas were inspected: training, (Cont. on next page)

PLANT SITE APPLICABILITY:

Docket No. 50-518

DESIGNATED ORIGINAL

Certified Excheance Clark

COVINGTON, OHIO

REPORT INSPECTION PAGE 2 of 4 RESULTS: NO .: 99900793/83-01

SCOPE: (Cont.) material identification and control, nonconformance, calibration, inspection, QA records, audits (internal/external), handling/ storage/shipping, and reporting of defects.

A. VIOLATIONS:

Contrary to Section 21.6 and Section 21.21 of 10 CFR Part 21, a current copy of 10 CFR Part 21 was not posted in the area where Section 206 was posted and required procedures had not been adopted to provide for the evaluation of deviations or for notification of the licensee or purchaser.

B. NONCONFORMANCES:

- Contrary to Criterion V of Appendix B to 10 CFR Part 50 and paragraph 5.3.2 and subparagraph 5.3.2.1 in Section 5.0 of the Identification and Verification Manual (IVM), a review of documentation and material for three inprocess nuclear contracts revealed that certain reels of wire were not identified with tags containing a control number. material descriptions, and weight for two of the contracts; i.e., three reels from Contract No. N-202 and three reels from Contract No. N-207 which were held, respectively, in the controlled material and nonconforming hold areas.
- Contrary to Criterion V of Appendix B to 10 CFR Part 50 and 2. paragraph 4.4.2 in Section 4.0 of the IVM, a review of the OA record files revealed that two vendors (Ohio Counting Scales and Eli Whitney Metrology Lab) performing testing services had been neither surveyed nor audited by Unibraze.
- Contrary to Criterion V of Appendix B to 10 CFR Part 50 and paragraph 7.9 in Section 7.0 of the IVM, a review of the QA record files revealed that a purchase order had not been sent nor had the applicable calibration procedure or standard to be used been otherwise provided to Ohio Counting Scales who had performed calibrations of weighing scales since 1975.
- 4. Contrary to Criterion V of Appendix B to 10 CFR Part 50 and Section QCF-8 of procedure QCI-12-76-2, a review of material in the nonconforming material hold area revealed that a reject tag attached to a reel of material for nuclear Contract No. N-207 was not signed by the individual responsible for attaching the tag.
- 5. Contrary to Criterion V of Appendix B to 10 CFR Part 50 and paragraphs 12.1.3 and 12.1.4 in Section 12.0 of the IVM, a review of internal audit activities for 1981 and 1982 revealed that: (a) an

COVINGTON, OHIO

REPORT NO .:

99900793/83-01

INSPECTION RESULTS:

PAGE 3 of 4

internal audit procedure did not exist, and (b) internal audit reports for 1981 and 1982 were not distributed to the applicable manager(s) of the areas being inspected.

C. UNRESOLVED ITEMS:

None

D. OTHER FINDINGS OR COMMENTS:

- 1. Mixed Diameter Electrodes -In March 1981, Tennessee Valley Authority (TVA) notified Unibraze that they had discovered 5/32" diameter electrodes intermixed with 1/8" diameter electrodes in 10 lb. canisters labeled 1/8" at the Hartsville nuclear site. All the material (approximately 9000 lbs. on Contract No. 76x72-523054-5) was returned to Unibraze for inspection. A 100 percent inspection revealed that approximately 10 percent of the 308L electrodes were intermixed in the canisters. Unibraze determined that the packaging error was due to similar lot numbers on the two different diameter electrodes. Unibraze modified procedures to prevent the packaging of like materials with similar control numbers. Chemical and mechanical tests were performed on the material, and the repackaged electrodes along with the certified material test reports were returned to TVA.
- 2. QA Program - A detailed review of documentation (e.g., QA manual, procedures, travelers, data packages, nonconformance reports, audit reports) led to the identification of five nonconformances (B above) and the following observations:
 - a. The QCF-16 form, "Specification and Contract Review Sheet," for nuclear Contract No. N-196 completed in 1982 was not signed and dated by a representative from the QA department.
 - b. The QCF-3 form, "Hold for Testing," for nuclear Contracts N-206 and N-207 was not filled in (e.g., invoice number plus date sample was taken) to indicate that the material was in a hold status awaiting test results.
 - c. The procedures manual did not have an index to indicate the revision and date of the applicable procedure in effect.
 - d. Procedures for quality affecting activities lacked sufficient detail for the activity being performed and were not posted at each work station.

COVINGTON, OHIO

REPORT		
NO.: 99900793/83-01 RESULT	TS: PAGE 4 of	

- e. Individuals performing dimensional and visual inspection were not required to satisfactorily pass an eye examination.
- f. The checklist used for internal audits was lacking in specificity to ensure that the QA program in a particular area was effective and properly implemented.

These observations were not considered as sufficiently severe deficiencies in the existing QA program or its implementation to be classified nonconformances, but were brought to the attention of appropriate Unibraze management personnel for their evaluation and follow up. These areas will be reexamined during a future inspection.

INSPECTOR JIM CONWAY SCOPE

DOCUMENTS EXAMINED

99900193 0 . 83 40 DOCKET NO. REPORT NO. PAGE

TTEM No.	TYPE OF DOCUMENT	DOCUMENT NO.	REV.	DATE	TINE / SUBJECT
-		1	2	2/21/82	IDENTIFICATION & VERIFICATION MANUAL
2	PRO	1	1	3/5/82	GA RECEDULES MANUAL
8	997	QCF-35	1		CONTROLLED MATERIAL RETRIEVAL LOG
4	907	9CF-33		18/22 /82	GA MANUAL LOS
S	907	١)	1	GA MANUAL PROCEPULES LOG
9	907		1	-1	GC INSTRUMENT TEST & MAINTENANCE RECORD
1	FIL	١)	١	TRAINING FILE (7/180 & 1/183)
00	FIL)	1	1	UNIBEARE APPROJED AUDITORS FILE
0	REP	í	1	1	INTERNAL AUDIT REPORTS FOR 1981 and 1982
01	REP	ì	1	1	MANAGEMENT AUDITS OF DA PROGRAM FOR 1981 (2) \$ 1982(2)
Ξ	820	1	1	1	AUDIT PROCEDURE FOR EXTERNAL AUDITS
1	O TH	ì	1	1	GA DATA PACKAGES FOR THREE NUCLEAR CONTRACTS IN-HOUSE
13	D TH	1	1	1	QA CATA PACKAGES FOR SIX NUCLEAR CONTINGETS COMPLETED IN 1982
4	DIM	-	1	11/18/82	APPROVED VENDOR'S LIST
15	REP)	1	1	EXTERNAL AUDIT REPORTS FOR 1982 FOR TEN UENDORS
-					

OF DOC: TYPE DWG - DRAWING SPEC - SPECIFICATION PRO - PROCEDUZE QAH - QA MANUAL GCD - QC DOCUMENT P.O. - PURCHASE ORDER INH - INTERNAL MEMO

LOG LETTER FILE KERET OIM - STARET

SCOPE JIM CONLUSES

DOCUMENTS EXAMINED

REPORT NO. 83 - 01

TTEN No.	TYPE OF DOCUMENT	DOCUMENT NO.	REV.	DATE	TITLE / SUBJECT
31	997	1	(NONCONFORMANCE REPORT ACCOUNTABILITY LOG FOR MATERIALS
17	REP	١	1	1	SIX NONCONFORMANCE REPORTS FOR NUCLEAR CONTRACTS
0)	REP)	1	1	TREND ANALYSIS REPORTS FOR SIX VENDORS
19	907	QCF-32	1	1	PROCEDURE CONTROL LOG
2	907	QCF-30	- 1	١	FORM CONTROL LOG
2	Ree	1	1	1	EXTERNAL AUDIT REPORTS FOR 1981 FOR THREE VENDORS

TYPE OF DOC:

DWG - DRAWING SPEC - SPECIFICATION PRO - PROCEDURE QAM - QA MANUAL GCD - QC DOCUMENT P.O. - PURCHASE ORDER INH - INTERNAL MEMO

8	1	-		1
LETTER	2717	KEPOR	67 MG	
,	1 1	-	1	1
LTR	3/2	KE	0	

PERSONS CONTACTED

Company UNIBRAZE CORP. Docket/Report No. 99900793 /83-01

Dates JAN 10 - 14 1983 Inspector JIM CONWAY

Page 1 of 1

NAME(Please Print)	TITLE(Please Print)	ORGANIZATION(Please Print
MARY WEIKERT *		UNIBRAZE CORP.
0/11	V. S. operations	Thisprane Corp.
Charles R miller	a.c ma	Making Rig
E.A PLANCK	DIR. EID	UNIBEATE CORP
ES. PAYNE +	U.P. HI-TEMP	11 2
B. HOWELL	FOREMAN - SHIPPING / RECEIDING	
L. BARGER	PLANT INSPECTOR	
P. BROWN	PRODUCTION SCHEDULER	
R. Gambin X	Asst. Sales Mer.	Unisraze Corp.
m Arouce +		Unibraze Copo
V 1	A S S S S S S S S S S S S S S S S S S S	
* ATTENDED EXIT	INCE TING	
Control of the Contro		