




GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 713 838-6631

March 1, 1983
RBG-14,482
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011



Dear Mr. Collins:

River Bend Station Units 1 and 2
Docket Nos. 50-458/I&E Bulletin 80-16
50-459/I&E Bulletin 80-16

On October 2, 1981, Gulf States Utilities Company (GSU) submitted a response to your office concerning I&E Bulletin 80-16, "Potential Misapplication of Rosemont, Incorporated Models 1151 and 1152 Pressure Transmitters With Either 'A' or 'D' Output Codes". Our response provided a summary of actions performed and actions to be taken. GSU was awaiting delivery of the last instrument so that General Electric could evaluate the instruments and perform any necessary corrective actions.

GSU is awaiting completion of GE's evaluation. It is currently estimated that a final report can be provided by May 3, 1983.

Sincerely,

William J. Booker
for J. E. Booker
Manager-Engineering,
Nuclear Fuels & Licensing
River Bend Nuclear Group

RJK
JEB/RJK/kt

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

R. L. Brown (SRI)

8303280230 830301
PDR ADCK 05000458
PDR

IEE
IEE