

APPENDIX A

NOTICE OF VIOLATION

Louisiana Power and Light Company  
Waterford Steam Electric Station

Docket: 50-382  
License: CPPR - 103

Based on the results of the NRC inspection conducted during the period of August 16-20, 1982, and in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C), 47 FR 9987 dated March 9, 1982, the following violation was identified:

10 CFR Part 50, Appendix B, Criterion V, states in part: Activities affecting quality shall be prescribed by documented instructions, procedures, or drawings, of a type appropriate to the circumstances and shall be accomplished in accordance with these instructions, procedures, or drawings.

Contrary to the above, an unspecified weld had been used to attach a plate to a diagonal horizontal angle brace at elevation 53' location 9' 9" North and 6' 9" West at column L-10 AZ instead of attaching the plate with bolting as specified by Ebasco Drawing G-842D.

This is a Severity Level V Violation. (Supplement II) (382/8218-01)

Pursuant to the provisions of 10 CFR Part 2.201, Louisiana Power and Light Company is hereby required to submit to this office, within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Dated: September 30, 1982

8210190437 820930  
PDR ADOCK 05000382  
PDR