



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401-1927
Telephone (612) 330-5500

June 8, 1994

NRCB 93-02 Supp 1

U S Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Follow-Up Response to NRC Bulletin 93-02 Supplement 1,
"Debris Plugging of Emergency Core Cooling Suction Strainers"

NRC Bulletin 93-02 Supplement 1, dated February 18, 1994, describes staff concerns related to the potential loss of Emergency Core Cooling Systems (ECCS) due to the possibility of suction strainer plugging and requested that licensees implement certain interim actions until the issue is resolved. Reporting Requirement No. 1 of the bulletin supplement required that all action addressees submit a written report indicating whether or not the addressee intends to comply with the actions requested therein, a description of the planned actions, and the schedule for completing them. NSP submitted information to satisfy this requirement in a letter to the NRC dated April 19, 1994. In that letter we committed to comply with the interim actions requested in the bulletin and described the actions already taken and several that remained to be completed to satisfy that commitment.

The remaining actions, which involved procedure changes and operator training, were completed on May 18, 1994. Reporting Requirement No. 2 of the bulletin supplement requires that all licensees submit, within 30 days of completion of the actions required by the bulletin supplement, a report confirming completion. As noted above all requested actions have been completed and this letter satisfies the second reporting requirement.

This letter contains no new NRC commitments. Please contact Terry Coss, Sr Licensing Engineer, at (612) 295-1449 if you require any additional information concerning this submittal.

Roger O Anderson
Director
Licensing and Management Issues

140657

9406140172 940608
PDR ADDCK 05000263
PDR

IE11
1/0

USNRC
June 8, 1994
Page 2

NORTHERN STATES POWER COMPANY

cc: Regional Administrator-III, NRC
NRR Project Manager, NRC
Resident Inspector, NRC
State of Minnesota,
Attn: Kris Sanda
J Silberg

Attachment (1): Affidavit to the US Nuclear Regulatory Commission

UNITED STATES NUCLEAR REGULATORY COMMISSION

NORTHERN STATES POWER COMPANY

MONTICELLO NUCLEAR GENERATING PLANT

DOCKET NO. 50-263


Follow-Up Response to NRC Bulletin 93-02 Supplement 1,
"Debris Plugging of Emergency Core Cooling Suction Strainers"

Northern States Power Company, a Minnesota corporation, hereby provides the required 30 day follow-up response information required by NRC Bulletin 93-02 Supplement 1.

This letter contains no restricted or other defense information.

NORTHERN STATES POWER COMPANY

By


Roger O Anderson
Director

Licensing and Management Issues

On this 5th day of June 1994 before me a notary public in and for said County, personally appeared Roger O Anderson, Director, Licensing and Management Issues, and being first duly sworn acknowledged that he is authorized to execute this document on behalf of Northern States Power Company, that he knows the contents thereof, and that to the best of his knowledge, information, and belief the statements made in it are true and that it is not interposed for delay.



