

OCT 14 1982

Detroit Outpatient Nuclear Clinic
ATTN: Robert H. Povlitz
Administrator
19050 West McNichols
Detroit, MI 48219

License No. 21-17011-01

Gentlemen:


This refers to the special safety inspection conducted by Mr. R. E. Burgin of this office on September 15, 1982, of activities authorized by NRC Byproduct Material License No. 21-17011-01 and to the discussion of our findings with you at the conclusion of the inspection.

This special inspection was initiated following the receipt of allegations pertaining to unsafe handling and/or storage of licensed byproduct material and concerns for patients in the vicinity of your nuclear medicine "hot lab." This inspection consisted of an examination of your facilities, including observations, independent measurements, and interviews with personnel. None of the general allegations were substantiated.

No items of noncompliance with NRC requirements were identified during the course of this inspection.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



D. J. Sreniawski, Chief
Materials Radiation Protection
Section 2

cc: DMB/Document Control Desk (RIDS)

RIII *[Signature]*
Burgin/sv
10/6/82

RIII *[Signature]*
Sreniawski
10/14/82

RIII
Miller
[Signature]

8210250089 821014
NMS LIC30
21-17011-01 PDR

IE HQ File Copy
DMB IE-07