## Appendix

## NOTICE OF VIOLATION

Hercules, Incorporated

License No. 24-20161-01

As a result of the inspection conducted on September 29, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified:

10 CFR 19.11(a) and (b) require that current copies of Part 19, Part 20, your license, license conditions, documents incorporated into the license, license amendments and operating procedures be posted, or that a notice describing these documents and where they may be examined, be posted.

Contrary to this requirement, on the day of the inspection, September 29, 1982, neither the documents nor the notices were posted.

This is a Severity Level V violation (Supplement VI).

The inspection showed that action had been taken to correct the identified item of noncompliance and to prevent recurrence. Consequently, no reply to this item of noncompliance is required and we have no further questions regarding this matter.

D. G. Wiedeman, Chief Materials Radiation Protection Section 1

10-12-82

Dated