

OCT 13 1982

Pittsburgh Testing Laboratory  
ATTN: W. H. Levelius  
Vice President  
850 Poplar Street  
Pittsburgh, PA 15220

License No. 37-00276-25

Gentlemen:

This refers to the special safety inspection conducted by Ms. E. Matson of this office on August 10, 1982, of activities authorized by NRC Byproduct Material License No. 37-00276-25 and to the discussion of our findings with Mr. R. D. Biacella at the conclusion of the inspection and with Mr. E. Andresky by telephone on September 10, 1982.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in non-compliance with NRC requirements, as specified in the enclosed Appendix. A written response is required.

The responses directed by this letter (and the accompanying Notice) are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

J. R. Miller, Chief  
Technical Inspection Branch

Enclosures:

1. Appendix, Notice of Violation
2. Inspection Report No. 30-5985/82-01(DETP)

cc w/encls:

John Kinneman, Region I  
DMB/Document Control Desk (RIDS)

RIII

Matson/np  
9/30/82

RIII

Sreniawski

RIII

Miller

8210250166 821013  
NMS LIC30  
37-00276-25 PDR

1E HQ file copy  
DMB 1E-07