



Northern States Power Company

414 Nicollet Mall  
Minneapolis, Minnesota 55401  
Telephone (612) 330-5500

October 15, 1982

Regional Administrator  
Region III  
U S Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

PRAIRIE ISLAND NUCLEAR GENERATING PLANT  
Docket No. 50-282 License No. DPR-42

Failure of 22 Diesel Cooling  
Water Pump to Start after Maintenance

The License Event Report for this occurrence is attached.

This event is reported in compliance with Technical Specification 6.7.B.2.(b) since it placed the plant in a degraded mode as permitted by limiting conditions of operations.

David Musolf  
Manager of Nuclear Support Services

DMM/SAF/js

cc: NRC Document Control Desk (1)  
NRC Resident Inspector  
MPCA  
Attn: J W Ferman

8210250179 821015  
PDR ADDCK 05000282  
S PDR

OCT 18 1982

LE 22