

30-2283

OCT 13 1982

St. John's Mercy Medical Center  
ATTN: John T. Farrell  
Executive Vice President  
615 South New Ballas Road  
St. Louis, MO 63141

License No. 24-00794-03  
License No. SNM-1752

70-2650

Gentlemen:

This refers to the routine safety inspection conducted by Mr. R. E. Burgin of this office on September 27, 1982, of activities authorized by NRC Byproduct Material License No. 24-00794-03 and Special Nuclear Material License No. SNM-1752 and to the discussion of our findings with you and members of your staff at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

In addition to the above areas, the inspector examined actions described in your letters dated October 11, 1978 and May 7, 1980, regarding apparent items of noncompliance found during our August 1978 and January 1980, inspections. We have no further questions regarding these matters.

No items of noncompliance with NRC requirements were identified during the course of this inspection.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



D. G. Wiedeman, Chief  
Materials Radiation Protection  
Section 1

cc: George Oliver, Ph.D.  
Radiation Safety Officer  
DMB/Document Control Desk (RIDS)

RIII  
Burgin/sv  
10/8/82

RIII  
Wiedeman  
10/12/82

IE HQ FILE COPY

DMB:IE07

8210250190 821013  
PDR ADOCK 07002650  
C PDR