

October 13, 1982

Mr. J. G. Keppler, Regional Administrator Office of Inspection and Enforcement, Region III U. S. NUCLEAR REGULATORY COMMISSION 799 Roosevelt Road Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

DOCKET NO. 50-266 LICENSEE EVENT REPORT NO. 82-015/03L-0 POINT BEACH NUCLEAR PLANT, UNIT 1

Enclosed is Licensee Event Report No. 82-015/03L-0 (a 30-day follow-up report) with an attachment which provides a description of an event reportable in accordance with Technical Specification 15.6.9.2.B.4, "Abnormal degradation of systems other than those specified in 15.6.9.2.A.3 (fuel cladding, reactor coolant pressure boundary, or primary containment) designed to contain radioactive material resulting from the fission process."

Very truly yours,

autar

Assistant Vice President

OCT 18 1982 DE22

C. W. Fay

Enclosure

Copy to NRC Resident Inspector

8210250258