

POST OFFICE EOX 2951 + BEAUMONT, TEXAS 77704 AREA CODE 713 838-6631

> April 19, 1983 RBG-14,833 File Nos. G9.5, G9.25.1.1

> > APR 2 1 1983

TE-27

Mr. John T. Collins, Regional Administrator U. S. Nuclear Regulatory Commission Region IV, Office of Inspection and Enforcement 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011

Dear Mr. Collins:

River Bend Station Unit 1 Docket No. 50-458 Interim Report/DR-71

On August 27, 1982, Gulf States Utilities Company (GSU) notified Region IV of a condition potentially reportable under 10CFR50.55(e) concerning inconsistencies found in the QA program at the W. J. Woolley Company, the manufacturer of GSU's personnel air locks (DR-71). GSU has not completed its evaluation. Our architect-engineer is awaiting information from W. J. Woolley Company. An interim or final status report will be submitted by June 3, 1983.

Sincerely,

Ε. Booke

Manager-Engineering, Nuclear Fuels & Licensing River Bend Nuclear Group



cc: Director of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

R. L. Brown (SRI)

8304260175 830419 PDR ADDCK 05000458 S PDR