



Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101 • 215 / 770-5151

October 14, 1982

Mr. R.C. Haynes
Director, Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

SUSQUEHANNA STEAM ELECTRIC STATION
LICENSEE EVENT REPORT 82-026/01P-0
ER 100450 FILE 841-23
PLA- 1345

Docket No. 50-387
License No. NPF-14

Dear Mr. Haynes:

This transmission confirms the telephone report of October 13, 1982 by L.D. O'Neil to Mr. E.C. McCabe of your staff, regarding the failure to complete grounding of Reactor Protection System cabling, as stated in Construction Deficiency Report 80-00-28, prior to fuel loading. This requirement was included in attachment 1 to Operating License NPF-14.

This condition is considered reportable in accordance with Operating License NPF-14, item 2.G.a.

H.W. Keiser
Superintendent of Plant-Susquehanna

DGM/cw

cc: Richard C. DeYoung - Director, Office of Inspection and Enforcement
Norman H. Haller - Director, Office of Management and Program Control
U.S.N.R.C. - Resident Inspector, Susquehanna SES

821025 0347 S

1E39