

DESIGNATED ORIGINAL

Certified By

mal

YANKEE ATOMIC ELECTRIC COMPANY



Rowe, Massachusetts 01367

October 12, 1982

United States Nuclear Regulatory Agency
Office of Inspection and Enforcement
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

Attention: Mr. R. C. Haynes

Dear Mr. Haynes:

Pursuant to the requirements of Technical Specifications, Section 6.9.4.a(3) the following is reported as Licensee Event Report 50-29/82-33.

As stated in the telephone report recorded at 1119 hours on 10/11/82, the No. 1 main coolant pump vent isolation valve weld was observed to be slightly moist on October 9, 1982. This weld will be repaired during the current refueling outage.

A more detailed report will follow within 14 days.

Very truly yours,

Herbert A. Antio
Plant Superintendent

HAA

/
meg

8210260106 821012
PDR ADOCK 05000029
S PDR

IEV