

OCT 14 1983

License No. 29-18207-01, 29-21430-01
Docket No. 030-14658, 030-20772
Control No. 15335, 15360

Fabco Piping Inc.
ATTN: John Bentivegna
Chief Inspector
1000 South 4th Street
Harrison, New Jersey 07029

Gentlemen:

Enclosed is Amendment No. 01 to terminate License No. 29-18207-01 and License No. 29-21430-01. You should review License No. 29-21430-01 for correctness and to assure that any changes in procedures required by the conditions are implemented.

We wish you success with your licensed program.

Sincerely,

Original Signed By
John E. Glenn, Ph.D.

John E. Glenn, Ph.D., Chief
Nuclear Materials Section B
Division of Engineering and
Technical Programs

Enclosures:

1. Amendment No. 01
2. License No. 29-21430-01
3. Form NRC-3
4. Form NRC-313(I)

9406170150 930728
PDR FOIA
THOMAS93-199 PDR

OFFICE	RI:DETP	RI:DETP				
SURNAME	Varela/k1	Glenn				
DATE	10/3/83	10/12/83				

150

Handwritten initials/signature

TELEPHONE OR VERBAL CONVERSATION RECORD

2-15-25

TIME 1000 8 A.M. P.M.

INCOMING CALL

OUTGOING CALL

VISIT

PERSON CALLING

J. McFadden

OFFICE/ADDRESS

R.I. DRESS

PHONE NUMBER | EXTENSION

215
337-5397

PERSON CALLED

J. Bentivegna

OFFICE/ADDRESS

Fabco
Harrison NJ

PHONE NUMBER | EXTENSION

201
481-7300

CONVERSATION

SUBJECT

SUMMARY

Licensed. RAM has been received
under lic. no. 29-21430-01

REFERRED TO:

ACTION REQUESTED

ADVISE ME OF ACTION TAKEN.

INITIALS

DATE

ACTION TAKEN

INITIALS

DATE

Handwritten initials/signature

DESIGNATED ORIGINAL

SAFETY INSPECTION

Certified By: *Brenda Platchek*

1. LICENSEE

*Fabco Piping Inc.
Harrison, NJ 07029*

2. REGIONAL OFFICE

RI:KOP

3. DOCKET NUMBER(S)

030-20772

4. LICENSE NUMBER(S)

29-21430-01

5. DATE OF INSPECTION

3-19-85

Licensee:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission's (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews, with personnel, and observations by the inspector. The findings as a result of this inspection are as follows:

- 1. Within the scope of this inspection, no violations were observed.
- 2. The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on those actions at this time.
- 3. During this inspection certain of your activities, as checked below, were in violation of NRC requirements.
THIS IS A NOTICE OF VIOLATION which is required to be posted in accordance with 10 CFR 19.11.
 - A. _____ was not properly posted to indicate the presence of a _____ 10 CFR 20.203(b), (c), (d), (e) or 34.42.
 - B. Containers located in _____ were not properly labeled to indicate the presence of radioactive material. 10 CFR 20.203(f)(1), or (f)(2).
 - C. _____ of sealed sources were not performed at the proper frequencies. 10 CFR _____ License Condition Number _____
 - D. Records of _____ were not properly maintained. 10 CFR _____ or License Condition Number _____
 - E. Documents were not properly posted or otherwise made available. 10 CFR 19.11.
 - F. Reports or notifications of _____ were not made in accordance with 10 CFR _____ or License Condition Number _____
 - H. _____
 - I. _____
 - J. _____
 - K. _____

*B504050030 B50319
REG 1 LIC 30
29-21430-01 PDR*

I hereby state that within 30 days the actions described by me to the inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC.

SIGNATURE - LICENSEE

DATE

SIGNATURE - NRC INSPECTOR

DATE

J McFadden

3/19/85

RETURN ORIGINAL TO
REGION I

IE:CT d.

A/14

CONVERSATION RECORD

TIME
Various

DATE
10/18/88

TYPE

VISIT

CONFERENCE

TELEPHONE

INCOMING

OUTGOING

Location of Visit/Conference:

NAME OF PERSON(S) CONTACTED OR IN CONTACT WITH YGU

ORGANIZATION (Office, dept., bureau, etc.)

TELEPHONE NO.

Fabco Piping, Inc.

(201) 481-7300

SUBJECT

Pending need for Renewal of License No. 29-21430-01

ROUTING

NAME/SYMBOL	INT

SUMMARY

AM No connection Telephone number had been disconnected.

AM Harrison Tax Assessors (201) 268-2448. Location's street address changed to 1000 Rogers Boulevard South. Owner of property was Guyon Piping Corp. They rented various parts of facility out and Fabco was not in their files.

PM Guyon General Piping, Inc. (201) 485-5600 representative stated that Fabco Piping had rented some office and industrial space from them but had moved out of the complex. They would check into the matter further.

10/9/88 Contacted Texas Nuclear. They have had no contact with the licensee since 1981. Sources have not been returned.

10/18/88 Ron Spangler ((212) 466-2285), authorized user of the licensed material while in the employ of Fabco Piping contacted me (10:20am). He stated that Fabco had suspended operations as of June, 1988 and that the equipment was in

ACTION REQUIRED

Telephone Inquiry Letter (Not sent)

NAME OF PERSON DOCUMENTING CONVERSATION

SIGNATURE

DATE

Steven Courtemanche

Steven Courtemanche

10/18/88

ACTION TAKEN

SIGNATURE

TITLE

DATE

50271-101

U.S. G.P.O. 1983-361-526/8346

CONVERSATION RECORD

OPTIONAL FORM 271 (12-76)
DEPARTMENT OF DEFENSE

AMS

all likelihood still there. He won't have to speak
with a representative from Guyon in order to obtain
permission to go on the premises and see if the
device was still there. He said that he would get back
in touch with me.

CONVERSATION RECORD

TIME

9:50

DATE

2/27/89

TYPE

VISIT

CONFERENCE

TELEPHONE

INCOMING

OUTGOING

ROUTING

NAME/SYMBOL	INT

Location of Visit/Conference:

NAME OF PERSON(S) CONTACTED OR IN CONTACT WITH YOU

Ron Spangler

ORGANIZATION (Office, dept., bureau, etc.)

Synergy Systems Corp

TELEPHONE NO.

212-466-2285

SUBJECT

status of Labco Rysing, Inc.

SUMMARY

Mr Spangler stated that the company is out of business. The licensed material is still in the building. He has been in touch with Texas Nuclear to dispose of the material. The building is owned by Guyon General Rysing. The building is locked and a security force patrols it. The material is secured. There is no parent company. Synergy Systems Inc. was a former sister company to Labco. Correspondence referring to this license should go to Ron Spangler.

Synergy Systems Corp.

ATTN: Mr. Ronald Spangler
President.

#1 World Trade Center, Suite 3000
NY, NY 10048.

ACTION REQUIRED

send Exp lic NOV.

NAME OF PERSON DOCUMENTING CONVERSATION

SIGNATURE

Marene Taylor

DATE

2/27/89

ACTION TAKEN

SIGNATURE

TITLE

DATE

A/16