NRC FORM 501 PART 1 (7-91)		U.S. NUCL	EAR REGULATORY COMMISSION
10 CFR 2.201	SAFETY IN	ISPECTION	
			Page 1 of
1. LICENSEE Veterans Administra 1900 Blackhoise P Contesy. He, Penns	ation Hespital	REGIONAL OFFICE REGION I U S NUCLEAR REGULATOI 475 ALLENDALE ROAD KING OF PRUSSIA PA 194	
3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)	5. DATE OF INSPE	CTION
030 -03127	37-10509-0	moy 12.1	994
Regulatory Commission (NRC) rules an procedures and representative records. fellows:   1. Within the scope of this inspected of this inspected and representative records.   2. The inspector also verified the questions on those actions at   3. During this inspection certain	d regulations and the conditions of interviews with personnel, and obs ction, no violations were observed. steps you have taken to correct th this time.	license as they relate to radiation safety a f your license. The inspection consisted of iervations by the inspector. The findings a ne violations identified during the last inspe- tow or attached, were in viciation of NRC re dance with 10 CFR 19.11.	f selective examinations of as a result of this inspection are at ection. We have no further
Aindicate the presence o	f a	. 10 0	ot properly posted to CFR 20.203(b),(c),(d),(e) or 34.42. led sources were not
C. Records of			e not properly maintained.
	operly posted or otherwise made a		
10 CFR	of or License Condition Num	iber	not made in accordance with
DESIGNATED OR Certified by:	RETURN	ORIGINAL TO	IE:67 0 1
above. This statement of corrective act unless required by the NRC.	actions described by me to the insp ions is made in accordance with th	pector will be taken to correct the violation requirements of 10 CFR 2.201. No furth	s identifier in the items checked er response will be submitted
uness required by the terro.		A REAL PROPERTY AND A REAL	