P.O. BOX 529100 MIAMI, FL 33152



FLORIDA POWER & LIGHT COMPANY

3 APR

28

AS

-

20

NRO

April 19, 1983 PNS-LI-83-282-1

Mr. James P. O'Reilly Regional Administrator, Region II U.S. Nuclear Regulatory Commission 101 Marietta Street N.W., Suite 2900 Atlanta, Georgia 30303

Dear Mr. O'Reilly:

## REPORTABLE OCCURRENCE 250-83-06

TURKEY POINT UNIT 3

DATE OF OCCURRENCE: APRIL 5, 1983

TECHNICAL SPECIFICATION 6.9.2.a.9

CONTROL BUILDING MASONRY WALLS

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide prompt notification of the subject occurrence.

Very truly yours,

Willaut.

J. W. Williams, Jr. Vice President Nuclear Energy

JWW/PLP/js

Attachment

cc: Director, Office of Inspection and Enforcement (40)
Harold F. Reis, Esquire
File 933.1 TP

8304280239 830419 PDR ADDCK 05000250 S PDR

PEOPLE .... SERVING PEOPLE

JE 22