

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | C I A R I S I S 1 | 2 | 0 0 0 - 0 0 0 0 0 0 - 0 0 0 | 3 | 4 1 1 1 1 | 4 | _____ | 5

CON'T
0 1 | REPORT SOURCE | L | 6 | 0 5 0 0 0 3 1 2 | 7 | 0 3 1 8 8 3 | 8 | 0 4 1 2 8 3 | 9

0 2 | EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
Surveillance tests on the Reactor Building Purge Discharge Fan A-536 Carbon
0 3 | Adsorber Filter Bank and the Auxiliary/Spent Fuel Building Filter System
0 4 | A-542B were below Tech Spec required efficiencies for Methyl Iodide removal.
0 5 | Since the reactor was in a defueled condition and A-542A was available,
0 6 | there were no effects on plant or public safety.
0 7 |
0 8 |

0 9 | SYSTEM CODE: A A (11) CAUSE CODE: E (12) CAUSE SUBCODE: X (13) COMPONENT CODE: F I L T E R (14) COMP SUBCODE: Z (15) VALVE SUBCODE: Z (16)
17 | LER/RO REPORT NUMBER: _____ EVENT YEAR: 8 3 (21) SEQUENTIAL REPORT NO.: 0 1 3 (24) OCCURRENCE CODE: 0 3 (28) REPORT TYPE: L (30) REVISE ON NO.: 0 (32)
ACTION TAKEN: X (18) FUTURE ACTION: X (19) EFFECT ON PLANT: Z (20) SHUTDOWN METHOD: Z (21) HOURS: 0 0 0 0 (22) ATTACHMENT SUBMITTED: Y (23) NPRO-4 FORM SUB: N (24) PRIME COMP SUPPLIER: L (25) COMPONENT MANUFACTURER: 8 0 7 1 5 (27)

1 0 | CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
The charcoal will be replaced with new charcoal by June 1, 1983.
1 1 |
1 2 |
1 3 |
1 4 |

1 5 | FACILITY STATUS: H (28) % POWER: 0 0 0 0 (29) OTHER STATUS: N/A (30) METHOD OF DISCOVERY: B (31) DISCOVERY DESCRIPTION: Surveillance test (32)

1 6 | ACTIVITY CONTENT RELEASED OF RELEASE: Z (33) Z (34) AMOUNT OF ACTIVITY: N/A (35) LOCATION OF RELEASE: N/A (36)

1 7 | PERSONNEL EXPOSURES NUMBER: 0 0 0 0 (37) TYPE: Z (38) DESCRIPTION: N/A (39)

1 8 | PERSONNEL INJURIES NUMBER: 0 0 0 0 (40) DESCRIPTION: N/A (41)

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE: Z (42) DESCRIPTION: N/A (43) 8305030290 830412 PDR ADOCK 05000312 S PDR

2 0 | PUBLICITY ISSUED: Y (44) DESCRIPTION: Local newspapers and wire services. (45) NRC USE ONLY

NAME OF PREPARER: R. W. Colombo PHONE: (916) 452-3211