

40-6659

Petrotomics Company

P.O. Box 8509, Shirley Basin, Wyoming 82615 · Telephone: (307) 234-9341

June 15, 1994

U.S. Nuclear Regulatory Commission  
Division of Waste Management M.S. 5 E2  
Attn: Joseph J. Holonich, Chief  
High Level Waste and Uranium  
Recovery Projects Branch  
11555 Rockville Pike  
Rockville, MD 20850

Reference: License Condition 47D  
Source Material License SUA-551

Dear Mr. Holonich:

In accordance with the requirements of License Condition 47D, submitted herewith in triplicate is our report which reviews the corrective action program and its effect on the aquifer.

Sincerely,

*R. A. Juday* / *[Signature]*

R. A. Juday  
Supervisor

Enclosure: Review of Corrective Action in the Upper Wind River Sand at Petrotomics' Tailings Area - 3 copies

cc: U.S. Nuclear Regulatory Commission  
Region IV  
Attn: Samuel J. Collins, Director  
Division of Radiation Safety and Safeguards  
611 Ryan Plaza Drive, Suite 400  
Arlington, TX 76011

2101

9406210254 940615  
PDR ADOCK 04006659  
B PDR

Cert # 4 P427 318 584

NL05 1/2