



Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101 • 215 / 770-5151

April 21, 1983

Mr. J.M. Allan
Acting Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

SUSQUEHANNA STEAM ELECTRIC STATION
LICENSEE EVENT REPORT 83-051/03L-0
ER 100450 FILE 841-23
PLA- 1632

Docket No. 50-387
License No. NPF-14

Dear Mr. Allan:

Attached please find a copy of Licensee Event Report No. 83-051/03L-0. This event was determined to be reportable per Technical Specification 6.9.1.9.b, in that the Reactor Core Isolation Cooling Pump turbine tripped on its electrical overspeed signal when automatically initiated.

H.W. Keiser
Superintendent of Plant-Susquehanna

LAK/pjg

attachment

cc: Director of Nuclear Reactor Regulation
Attention: Mr. A. Schwencer, Chief
Licensing Branch No. 2
Division of Licensing
U.S. Nuclear Regulatory Commission
Washington, DC 20555

G.G. Rhoads
Resident Inspector
U.S. Nuclear Regulatory Commission
P.O. Box 52
Shickshinny, PA 18655

8305030334 830421
PDR ADOCK 05000387
S PDR