



Commonwealth Edison
Zion Generating Station
Shiloh Blvd. & Lake Michigan
Zion, Illinois 60099
Telephone 312/746-2084

November 24, 1982

- Mr. James G. Keppler
Regional Director
Directorate of Regulatory Operations
Region III
U.S. Nuclear Regulatory Commission
Glen Ellyn, Illinois 60137

Reference: Zion Generating Station
Docket No. 50-295/DPR-39
Technical Specification, Section 3.21.2.B

Dear Mr. Keppler,

Enclosed please find a Special Report No. 50-295/82-40 which pertains to Zion Generating Station's fire pump.

This report is submitted to you in accordance with the requirements of the Technical Specifications, Section 3.21.2.B which states; "When it is determined that less than two fire pumps and their associated initiation logic circuits are operable, the inoperable equipment shall be restored to operable status within 7 days, or in lieu of any other report required by Specification 6.6.2, prepare and submit a Special Report to the Commission within the next 30 days outlining the plans and procedures to be used to provide for the loss of redundancy in this system".

Very truly yours,

K. L. Graesser
Superintendent
Zion Station

Enclosure: Reportable Occurrence Report 82-40/99X-0