LASALLE COUNTY NUCLEAR GENERATING STATION N.P.D.E.S. PERMIT NO: IL0048151 NONCOMPLIANCE REPORT

DISCHARGE NUMBER AND DESCRIPTION:

Outfall OOlc Low Volume Waste

Regen. Wastes Sold. Discharge Tank

PARAMETER AND PERMIT LIMIT: Total Suspended Solids, 15.0 mg/1

Total Iron, 1.0 mg/l

NONCOMPLIANCE, DATE, AND DURATION: Total Suspended Solids, 45.7 mg/1, 29 October 1982

52,497 gallons

Total Iron, 41.3 mg/1, 29 October 1982, 52,497

gallons

CAUSE OF NONCOMPLIANCE:

1110

The normal influents to this tank contain iron concentrations of less than 5 mg/l iron as verified by sampling on 11/11/82. The most probable cause of the high iron concentration was the addition to the tank of construction wastes from the Unit 2 condensate polishing system.

CORRECTIVE ACTION:

A modification has been initiated to provide the option for treatment of these tanks in the Waste Water Treatment Facility. The modification should be implemented by February 1983.

DATE RECOGNIZED AS A VIOLATION:

DATE INVESTIGATED:

PDR

8212020282 821123 PDR ADOCK 05000373

1 November 1982

12 November 1982