

APR 13 1989

Q. C. Services
Division of World Technical Services, Inc.
23101 Foley Street
Hayward, California 94545

Attention: Mr. Robert Williamson
President

Gentlemen:

Please find enclosed NRC Form-591 which indicates three violations that were identified during the safety inspection conducted on April 13, 1989 of activities authorized by NRC License No. 04-14875-02.

Pursuant to the provisions of 10 CFR 2.202, you are requested, within 30 days, to sign and date the enclosed NRC Form-591 which indicates that appropriate corrective action will be taken with reference to the violations described on the form. After signing, please detach the first sheet of NRC Form-591 and return the remaining carbon copies with your signature to me at the Region V office.

If you have any questions relative to this matter or concerning this inspection, please feel free to call me at 415-943-3700.

Thank you for your cooperation.

Sincerely,

original signed by

J. Frank Pang
Radiation Specialist

Enclosure: NRC Form-591

bcc w/o Encl: Central Files, RV

RV JFP
FPang/cb
4/21/89

91-1090408 900822
PDR FOIA
FELTON90-328 PDR