

SEP 19 1989

License No.: 50-23363-01

Ultra Technology, Inc.
3836 Brighton Drive, N. W.
Calgary, Alberta, Canada T2L 1G8

Attention: Mr. Donald S. Heiken
Radiation Safety Officer

Gentlemen:

Please find enclosed NRC Form-591 which indicates two violations that were identified during the safety inspection conducted on August 17, 1989 of activities authorized by NRC License No. 50-23363-01.

Pursuant to the provisions of 10 CFR 2.202, you are requested, within 30 days, to sign and date the enclosed NRC Form-591 which indicates that appropriate corrective action will be taken with reference to the violations described on the form. After signing, please detach the first sheet of NRC Form-591 and return the remaining carbon copies with your signature to me at the Region V office.

If you have any questions relative to this matter or concerning this inspection, please feel free to call me at 415-943-3700.

Thank you for your cooperation.

Sincerely,

Original signed by

Paul R. Zurakowski
Radiation Specialist

Enclosure: NRC Form-591

bcc w/o Encl: Central Files, RV

RV ^{PRZ}
PZurakowski/cb

9/ 19 /89

9101100009 900822
PDR FOIA
FELTON90-328 PDR