

CP&L

Carolina Power & Light Company

P. O. Box 101, New Hill, N. C. 27562
November 30, 1982

Mr. James P. O'Reilly
United States Nuclear Regulatory Commission
Region II
101 Marietta Street, Northwest (Suite 3100)
Atlanta, Georgia 30303

NRC-27

CAROLINA POWER & LIGHT COMPANY
SHEARON HARRIS NUCLEAR POWER PLANT
1985-89 - 900,000 KW - UNITS 1 & 2
AUXILIARY RELAY CABINETS, NY-435246, ITEM 105

Dear Mr. O'Reilly:

On November 1, 1982, Mr. A. Hardin of the NRC was notified of a potentially reportable item per the provisions of 10CFR50.55(e). Mr. Hardin was informed that the auxiliary relay cabinets supplied by Systems Control Corporation have welding deficiencies. It was reported that this item was not reportable per the provisions of 10CFR, Part 21; this, however, after further evaluation, is not correct. This item is also considered potentially reportable per 10CFR, Part 21.

At the present time, the vendor is still evaluating the cabinets and do not expect to be complete with a reanalysis until the end of January. In addition, the vendor is supplying revised drawings identifying critical welds so a reinspection of the cabinets can be performed. For this reason, we would request an extension until February 4, 1983 for submitting a report on the reportability of this item.

Yours very truly,



R. M. Parsons
Project General Manager
Shearon Harris Nuclear Power Plant

RMP/sh

cc: Mr. G. Maxwell (NRC-SHNPP)
Mr. V. Stello (NRC)

50-400
50-401

OFFICIAL COPY
IE 27

8212070305 821130
PDR ADOCK 05000400
S PDR