Official Record

JUN 09 1994

Docket No. 030-28920 License No. 47-24807-01

Compton Construction Company ATTN: Mr. Milton C. Compton President P. O. Box 302C, Route #4 Princeton, WV 24740

Gentlemen:

SUBJECT: NOTICE OF VIOLATION

(NRC INSPECTION REPORT NO. 47-24807-01/94-01)

This refers to the inspection conducted by Mr. M. Fuller of this office on May 19, 1994. The inspection included a review of activities authorized for your Princeton, West Virginia facility. At the conclusion of the inspection, the findings were discussed with you.

The inspection was an examination of activities conducted under your license with respect to radiation safety and compliance with NRC regulations and the conditions of your license. It included selective examinations of procedures and representative records, interviews with personnel, and direct observations by the inspector.

Based on the results of this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice of Violation (Notice). We are concerned about the violations because they reflect a need for additional training of the Radiation Safety Officer (RSO) in NRC requirements. In your response to the Notice, include actions you have taken or plan to take to improve the knowledge of regulatory requirements possessed by your RSO. In addition, the inspector identified activities that violated NRC requirements that will not be subject to enforcement action because the licensee's efforts in identifying and/or correcting the violations meet the criteria specified in Section VII.B of the Enforcement Policy. The non-cited violations are failure to post copies of the NRC license, the application, 10 CFR Parts 19, 20, and 21, and failure to post a copy of Section 206 of the Energy Reorganization Act of 1974. These items were also discussed with you during the meeting at the conclusion of the inspection.

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. In your response, you should document the specific actions taken and any additional actions you plan to prevent recurrence. After reviewing your response to this Notice, including your proposed corrective actions and the results of future inspections, the NRC will determine whether further NRC enforcement action is necessary to ensure compliance with NRC regulatory requirements.

9406270078 940609 PDR ADOCK 03028920 C PDR

240112

型的

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter, its enclosure, and any reply will be placed in the NRC Public Document Room.

The responses directed by this letter and the enclosed Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, Pub. L. No. 96-511.

Should you have any questions concerning this letter, please contact us.

Sincerely,

Original Signed By D. M. Collins

Douglas M. Collins, Chief Nuclear Materials Safety and Safeguards Branch Division of Radiation Safety and Safeguards

Enclosure: Notice of Violation

cc w/encl: State of West Virginia

bcc w/encl: Document Control Desk RII Docket File, DRSS

SEND	OFC	RII:DRSS /	RII:DRSS		
то	NAME	Mfuller MA	CHOSEY CMA		
PDR?	DATE	06/26/94	06/ 9 /94	/ /94	/ /94
Yes No	COPY?	Tres No	Yes No.	Yes No	Yes No

OFFICIAL RECORD COPY / DOCUMENT NAME:G:\drss\nmis\comp.nov