

November 30, 1982

Mr. R.C. Haynes Director, Region I U.S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, PA 19406

SUSQUEHANNA STEAM ELECTRIC STATION LICENSEE EVENT REPORT 82-042/01T-0 ER 100450 FILE 841-23 PLA- 1414

Docket No. 50-387 License No. NPF-14

Dear Mr. Haynes:

Attached please find a copy of Licensee Event Report No. 82-042/01T-0. This event was determined to be reportable per Technical Specification 6.9.1.8.b, in that grab samples were not taken at the required frequency when the Residual Heat Removal Service Water System Radiation Monitor was inoperable.

Additionally, please note that the letter confirming the telephone notification of this occurrence (PLA-1337, dated 10/11/82) should carry the LER number 82-042/01P-0.

Treeses

H.W. Keiser Superintendent of Plant-Susquehanna

LAK/cw

cc: A. Schwencer
Division of Licensing
U.S. Nuclear Regulatory Commission
Washington, DC 20555

G. Rhoads Resident Inspector U.S. Nuclear Regulatory Commission P.O. Box 52 Shickshinny, PA 18655