

NOV 29 1982

Medical Associates
ATTN: Robert A. Boedecker, M.D.
Radiation Safety Officer
W180 N7950 Town Hall Road
Menomonee Falls, WI 53501

License No. 48-15939-01

Gentlemen:


This refers to the routine safety inspection conducted by Mr. R. E. Burgin of this office on November 9, 1982, of activities authorized by NRC Byproduct Material License No. 48-15939-01 and to the discussion of our findings with you and Ms. M. B. Riegert at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

No items of noncompliance with NRC requirements were identified during the course of this inspection.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



D. G. Wiedeman, Chief
Materials Radiation Protection
Section 1

cc: DMB/Document Control Desk (RIDS)

IE HQ FILE COPY

RIII
[Handwritten initials]
Burgin/jp
11/22/82

RIII
[Handwritten signature]
Wiedeman
11/23/82

8212080436 821129
NMS LIC30
48-15939-01 PDR

DMB:IE07