



CONNECTICUT YANKEE ATOMIC POWER COMPANY

HADDAM NECK PLANT

RR #1, BOX 127E, EAST HAMPTON, CONN. 06424

December 2, 1982

Mr. Ronald C. Haynes, Regional Administrator
Region 1, U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Reference: Facility Operating License No. DPR-61
Docket No. 50-213
Reportable Occurrence LER 82-10/3L

Dear Mr. Haynes:

This correspondence forwards the Licensee Event Report for Reportable Occurrence LER 82-10/3L, required to be submitted within 30 days, pursuant to the requirements of Connecticut Yankee Technical Specifications, Section 6.9.2.b.2.

An additional three copies of the report are enclosed.

Very truly yours,

Richard H. Graves
Station Superintendent

RHG:RZT/jhb

Attachment: LER 82-10/3L

cc: Dir., Office of Inspection and Enforcement, Washington, D. C. (30)
Dir., Office of Manag. Info & Program Control, Wash., D. C. (3)
USNRC c/o Document Management Branch, Washington, D. C. (1)