

Appendix

NOTICE OF VIOLATION

Department of Justice

License No. 48-17508-01

As a result of the inspection conducted on November 8, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified:


License Condition 13.A requires that your nickel-63 gas chromatograph detector cell be tested for leakage and/or contamination at intervals not to exceed six months.

Contrary to the above, your detector cell has not been leak tested since its receipt in 1976.

This is a Severity Level IV violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

12-1-82  
Dated

  
D. G. Wiedeman, Chief  
Materials Radiation Protection  
Section 1