

DEC 1 1982

Associated Analysts
ATTN: B. B. Elliott
11515 W. North Avenue
Milwaukee, WI 53226

License No. 48-18684-01

83814840

Gentlemen:

This refers to the routine safety inspection conducted by Mr. R. E. Burgin of this office on November 8, 1982, of activities authorized by NRC Byproduct Material License No. 48-18684-01 and to the discussion of our findings with Ms. M. Connardy at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in non-compliance with NRC requirements, as specified in the enclosed Appendix. A written response is required.

The responses directed by this letter (and the accompanying Notice) are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.


Sincerely,



D. G. Wiedeman, Chief
Materials Radiation Protection
Section 1

Enclosure: Appendix,
Notice of Violation

cc w/encl:
DMB/Document Control Desk (RIDS)

RIII 
Burgin/jp
11/22/82

RIII 
Wiedeman

12/1/82

IE HQ FILE COPY

8212080487 821201
NMS LIC30
48-18684-01 PDR

DMB:IE07