



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

December 2, 1982

JAMES P. McGAUGHY, JR.
ASSISTANT VICE PRESIDENT

Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Region II
101 Marietta St., N.W., Suite 3100
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station
Unit 1
Docket No. 50-416
License No. NPF-13
File 0260/L-835.0
Smoke Detectors Alarmed and
Would Not Reset
LER 82-119/03 L-0
AECM-82/585

During shutdown on November 4, 1982, the smoke detectors in the zone covering the Auxiliary Building East Corridor, elevation 103 feet, alarmed and would not reset. This report is being submitted pursuant to Technical Specification 3.3.7.9. Attached is LER 82-119/03 L-0.

Yours truly,

James P. McLaughly, Jr.
FOR J.P. McLaughly, Jr.

JPM:sap
Attachment

cc: Mr. N. L. Stampley (w/a)
Mr. R. B. McGehee (w/o)
Mr. T. B. Conner (w/o)
Mr. G. B. Tavlör (w/o)

Mr. Richard C. DeYoung, Director (w/a)
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Document Control Desk (w/a)
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

8212090074 821202
PDR ADOCK 05000416
S PDR

OFFICIAL COPY
IE 22