

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 M S G G S 1 00 - 000000 - 00 41111 5

CON'T REPORT SOURCE L 05000416 7110282 8120182 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
02 During cold shutdown on November 2, 1982, fire barrier penetrations to cabinets
03 1H13P700 A, B, D & E; 1H13P735A & B; and 1H13P714A & B, located in the Control
04 Building, elevation 166 feet, were broken in order to perform planned maintenance
05 activities. An LCO was entered in accordance with Technical Specification 3.7.7.
06 There was no effect on the health and safety of the public and no threat to plant
07 safety.

09 SYSTEM CODE AB 11 CAUSE CODE X 12 CAUSE SUBCODE Z 13 COMPONENT CODE ZZZZZZ 14 COMP. SUBCODE Z 15 VALVE SUBCODE Z 16
17 LER/RO REPORT NUMBER 82 21 22 SHUTDOWN METHOD 123 24 25 OCCURRENCE CODE 99 28 29 REPORT TYPE X 30 REVISION NO. 0 32
ACTION TAKEN X 18 FUTURE ACTION X 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0000 37 40 ATTACHMENT SUBMITTED N 23 NRC-4 FORM SUB. N 24 PRIME COMP. SUPPLIER Z 25 COMPONENT MANUFACTURER Z999 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
10 An hourly fire watch was established. The penetrations will be resealed
11 within two weeks. This is an interim report. An updated report will be
12 submitted by February 2, 1983.

15 FACILITY STATUS B 28 POWER 000 29 OTHER STATUS NA 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Planned Maintenance Activity 32
16 ACTIVITY CONTENT Z 33 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36
17 PERSONNEL EXPOSURES 000 37 Z 38 DESCRIPTION NA 39
18 PERSONNEL INJURIES 000 40 DESCRIPTION NA 41
19 LOSS OF OR DAMAGE TO FACILITY 3 42 DESCRIPTION NA 43
20 ISSUED DESCRIPTION N 44

8212090184 821201 PDR ADOCK 05000416 S PDR

NAME OF PREPARER Original signed by J. M. Floyd

PHONE