NRC FORM 366 (12-81)	LICENSEE EVENT REPORT	APPROVED BY OMB 3150-0011 EXPIRES 4-30-62
CONTROL BLOCK:	(PLEASE PRINT OR TYPE ALL	REQUIRED INFORMATION)
0 1 S C V C S 1 2 0 0	0 - 0 0 0 0 0 - 0 0 3 4 1 1	0 0 0 4 57 CAT 38 5
CON'T 0 1 REPORT I 6 0 5 0 0	0 0 3 9 5 7 1 1 0 3 8 2 8 T NUMBER 60 EVENT DATE 74	1 2 0 2 8 2 9
O 2 On November 3, 1982, the	consequences (10) e Plant entered Mode 3 with the Con	trol Room Evacuation
0 3 Panel Pressurizer Relief	f Tank Level Indicator (LI-470A) in	operable. The
0 4 condition was identified	d during surveillance testing prior	to mode change. Mode
o 5 change was permitted by	provision of Technical Specificati	on. There were no
0 6 adverse consequences as	the Technical Specification Action	Statement was
0 7 complied with.		
0 8		80
SYSTEM CODE CODE	12 13 19	P. VALVE SUBCODE 1 15 Z 16
LER/RO RVENT YEAR 17 REPORT 8 2 23 ACTION PUTURE EFFECT SHUTE ON PLANT METI A 18 Z 11 Z 20 Z 33 34 35 36	10 0 0 0 0 Y 23 N 24	PRIME COMP. COMPONENT SUPPLIER MANUFACTURER 26
CAUSE DESCRIPTION AND CORRECTIVE	EACTIONS ② LT-470A) for the subject indicator	was out of
[1] calibration. A Maintena	ance Work Request was issued for in	vestigation and
1 2 repair. The transmitter	r was calibrated. The applicable s	urveillance test was
1 3 performed satisfactorily	y, and the system was returned to o	perable status on
November 9, 1982.		80
1 5 B 28 0 0 0 29	N/A B 31 Operator Obser	vation 32
7 8 9 10 12 13 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACT		OF RELEASE 36
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION(1 7 0 0 0 37 Z 38 38 38 38 38 38 38 38 38 38 38 38 38	39 N/A	80
PERSONNEL INJURIES NUMBER DESCRIPTION 41	N/A	
TYPE DESCRIPTION 1 9 Z 42	N/A	86
PUBLICITY DESCRIPTION 45	N/A	NRC USE ONLY
NAME OF PREPARER	and the same of th	(803) 345-5209
DR ADDCK 05000395 PDR	H. C. Fields	